

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0005106	<b>CLAIM STATUS</b> Authorized	
BASDEN RV CENTER INC	<b>CLAIM</b> 1349802	
DBA AMERICAN RV CENTER	<b>CLAIM ORIGIN</b> WEB	
600 E BASELINE ROAD	<b>ORIGINAL CLAIM ID</b>	
EVANSVILLE, IN 47725	<b>VIN</b> 5ZT2CAUB5MX021147	
USA	<b>CHASSIS VIN</b>	
	<b>MILEAGE</b> 0	
<b>Labor rate:</b> \$150.00	<b>SITE/WAREHOUSE</b> 205 / 205	
<b>OWNER INFORMATION</b>	<b>ITEM #</b> ACAT293QBCKLE	
TELESA WADSWORTH	<b>DEALER RO #</b> 69509	
100 JACK CT	<b>CLAIM START DATE</b> 12/09/2022	
Odon, IN 47562	<b>CLAIM END DATE</b> 01/01/1900	
USA		
<b>Retail Date of Purchase</b> 03/30/2021	<b>WARRANTY EXPIRATION DATE</b> 03/30/2022	

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b> RC-003-22-00-004205	<b>Operational Description</b> 22V477, 2022-358 - BREAKAWAY SWITCH WIRING - INSPECT AND REWIRE - Recall/Electrical/Rewire/No Tread Code
	<b>Complaint, Cause, Correction</b>	
	Original Note : bhoffman@americanrvcenter.com, 2022-12-09 08:37:40 :: JOB #22V477 BRAKE AWAY SWITCH WIRING RECALL break away is not wired correctly, cut under belly and found large block of foam covering breakers and wires, have to cut foam out of way to get to terminals, remove break power wire and work out to disconnect, remove disconnect from frame and wire in breakaway to battery side of disconnect test brakes, install disconnect, tape up underbelly,	
	<b>Model #</b>	<b>Dlr Sub Hrs</b> 0.30 <b>Sub Labor Amt</b> \$45.00
	<b>Serial #</b>	<b>Appr Hrs</b> 0.30 <b>Appr Labor Amt</b> \$45.00
	<b>Notes</b>	
	Authorized as requested	

<b>Submitted</b>	Labor Amt	\$45.00		<b>Approved</b>	Labor Amt	\$45.00
	Parts & Freight	\$0.00			Parts & Freight	\$0.00
	Total	\$45.00			Total	\$45.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE \_\_\_\_\_  
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE \_\_\_\_\_  
All repairs described have been inspected and are satisfactory.