



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 69550

### CUSTOMER WORK ORDER

WO #: 69550  
Customer: 1000 - BASDENS  
AMERICAN RV -  
Tag:  
Author: BH  
Location: 0105 CHECK WORK

Stock #: 11161  
Stock Desc: 2023 TT KEYSTONE  
SPRINGDALE 286BHU  
Chassis #: 4YDTSGN28P3101691  
Serial #: 4YDTSGN28P3101691  
Mileage: 0  
Licence:

Invoice #:  
Date In: 15 DEC 22  
Promised:  
Date Sched:  
Completed: 21 DEC 22  
Warr. Date:

#### Job #PDINTT - Internal

COMPLAINT: Transferred to BAS\*69573 on 20 DEC 22  
Estimate amount was 0.00  
PDI - NEW TRAVEL TRAILER

CORRECTION: pdi done did everything on sheet.

#### Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DGH	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

#### Job #WINTER - Internal

COMPLAINT: Transferred to BAS\*69573 on 20 DEC 22  
Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.  
\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*  
UNITS WITH WASHING MACHINE OR ICEMAKER  
WILL BE EXTRA

\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*  
NUMBER OF GALLONS USED \_\_\_\_\_

CORRECTION: winterized.

#### Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DGH	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

#### Job #1 - Warranty

COMPLAINT: NO POWER TO THE OUTSDIE FRIDGE



Customer #:  
1000



CORRECTION: took drawer out and found 2 screws and took out ,had to take off bottom trim to pull out ref,pulled out and found ground was not hooked up,hooked up ground and it works,reinstalled ref and screwed down,reinstalled bottom wood trim.

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	60.00
<b>Subtotal for Job #1:</b>			<b>60.00</b>

**Job #2 - Warranty**

COMPLAINT: THE A/C PLENUM IS DAMAGED AND THE COVER IS BROKEN

CORRECTION: took plenum cover and plenum down and straightened plenum metal it was bent,had to fix wood bracing in ceiling it was broke,had to readjust divider in center it was to long,reinstalled metal plenum and long bolts and tightened up a/c,reinstalled cover,needs replaced it was broken when factory installed it.

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	75.00
Z990	MISCELLANEOUS REPAIR	RAB	15.00

**Parts**

Part #	Description	Qty	Price	Total
664434	CEILING KIT	1.00	76.48	76.48

**Other Services**

Code	Description	Qty	Price	Total
FRT	UPS-CEILING KIT	1.00	24.74	24.74

**Subtotal for Job #2: 191.22**

Parts Total:	76.48
Labour Total:	150.00
Sublet Total:	0.00
Extras Total:	24.74
<b>WORK ORDER TOTAL:</b>	<b>251.22</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 21 Dec 2022

W/O: 69550



Customer #: 1000

