

aim Response

12/19/2022  
05:50:31 pm

aim: C3296223

Last Modified by:stutk

| Item | Reference no. | Repair start date | Repair date | VIN | Pre-auth | Dealer Repairing dealer name | Labor rate | Changed Type | Date of Purchase |
|------|---------------|-------------------|-------------|-----|----------|------------------------------|------------|--------------|------------------|
|------|---------------|-------------------|-------------|-----|----------|------------------------------|------------|--------------|------------------|

|        |       |            |            |                   |      |                                                                   |        |      |                  |
|--------|-------|------------|------------|-------------------|------|-------------------------------------------------------------------|--------|------|------------------|
| 296223 | 69552 | 12/15/2021 | 12/15/2022 | 4YDFCGK27NV507381 | 1194 | Basden's American RV<br>600 E Baseline Rd<br>Evansville, IN 47725 | 150.00 | 0.00 | SA22-434 4/15/20 |
|--------|-------|------------|------------|-------------------|------|-------------------------------------------------------------------|--------|------|------------------|

| Item number | Name | Quantity | Qty Returned | Dealer price | Markup | Part total | Appr Freight | Sub Freight | Sublet | Status   |
|-------------|------|----------|--------------|--------------|--------|------------|--------------|-------------|--------|----------|
|             |      | 1.00     | 0.00         | 0.00         | 15.00  | 0.00       | 0.00         | 0.00        | 0.00   | Approved |

Component Model: V000231446 Component Serial Number: RPO-0008099958

| Operation | Description | Svc advisory | Sub hours | Apvd Hours | Labor amt | Sublet | Qty | Base Hours | Status |
|-----------|-------------|--------------|-----------|------------|-----------|--------|-----|------------|--------|
|-----------|-------------|--------------|-----------|------------|-----------|--------|-----|------------|--------|

|          |                                                                                              |  |      |      |       |      |   |      |          |
|----------|----------------------------------------------------------------------------------------------|--|------|------|-------|------|---|------|----------|
| 7143442K | Safety Advisory 22-434 Lippert A<br>Complaint: #22-434 LIPPERT AWNING RECALL<br>(INSPECTION) |  | 0.30 | 0.30 | 45.00 | 0.00 | 1 | 0.30 | Approved |
|----------|----------------------------------------------------------------------------------------------|--|------|------|-------|------|---|------|----------|

Cause: FOUND NO ISSISE WITH AWNING  
Correction: took pictures of awning,found no  
seperation or tears in awning. looks good as new

|                          |       |                         |       |
|--------------------------|-------|-------------------------|-------|
| Submitted parts & sublet | 0.00  | Approved parts & sublet | 0.00  |
| Submitted labor & sublet | 45.00 | Approved labor & sublet | 45.00 |
| Submitted freight:       | 0.00  | Approved freight        | 0.00  |
| Tax:                     | 0.00  | Tax:                    | 0.00  |
| Total Submitted:         | 45.00 | Total approved:         | 45.00 |