

e-Authorization

1/5/20
10:14:58

3-Authorization number PA03340014 Reference no: 69603 Status: Approved Approved by stuml Approved date 1/5/2023
rvicing Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDF37326MA740236 8/6/2020
600 E Baseline Rd
Evansville, IN 47725

lu Root Description Sublet Sub hours Approved Actual Qty Base Complaint / Cause / Correction
je operation of hours hours hours hours hours

1 7140942A Safety Advisory 2 0.00 1.00 0.50 1 Complaint:RECALL 21-409

It has been decided that the vehicles in the recall population may have 120VAC wiring connectors for the slide room circuit that can get wet and stay wet for extended periods of time due to the way they are mounted. Under certain conditions if the 120VAC connections are wet for an extended period of time it can lead to an increased risk of fire and/or damage to personal property. Cause:PULLED UNIT INTO SHOP. PULLED UNDERBELLY AND FOUND WIRES LAYING ON THE UNDERBELLY. Correction:DILLED OUT HOLE. SECURED BOARD TO INSIDE OF FRAME. TAPED UP UNDERBELLY. IT WAS THE DINETTE SLIDE

KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.

3-Authorization number PA03340014 0.50

r paper claims ~~only~~ use one pre-authorization number per warranty claim for
iple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the