

e-Authorization

1/17/20
02:55:19

3-Authorization number PA03344996			Reference no: 69646		Status: Approved		Approved by RassD		Approved date 1/12/2023	
rving alter		Name		Address		VIN		Retail sold on		
34		Basden's American RV		Basden's American RV 600 E Baseline Rd Evansville, IN 47725		4YDFHMT2XPA740065		10/27/2022		
lu Root e operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction		
1	6102915A Kitchen Sink - Rel	0.00	0.20	0.20		1	0.30	Complaint:THERE IS WATER LEAKING UNDER THE KITCHEN SINK. UNIT IS WINTERIZED. Cause:BAD CONE WASHER Correction:PRESSURED THE SYSTEM AND FOUND THE HOT WATER SIDE FITTING WAS DRIPPING I LOOSENED UP THE FITTING AND FOUND THE CONE WASHER DAMAGED AND LEAKING		
2	6100215A Bath Faucet - Ref	0.00	0.20			1	0.30	Complaint:THERE IS A WATER LEAK UNDER THE BATHROOM SINK. Cause:BAD CONE WASHER Correction:PRESSURED THE SYSTEM AND FOUND THE COLD SIDE WATER LINE WAS LEAKING AT THE FITTING I LOOSENED UP THE FITTING AND FOUND THE CONE WASHER DAMAGED AND LEAKING ALSO HAD TO TIGHTEN UP THE FAUCET IT WAS LOOSE ON THE COUNTER TOP		
KRV – Duplicate Pre-Authorization. Original Pre-Authorization was previously approved. PA03253955										
3	3103206B Drawer - Replace	0.00	0.40	0.40		1	0.20	Complaint:THE TOP DRAWER IN THE BATHROOM DOES NOT SHUT ALL THE WAY. Cause:THE TOP DRAWER IS VERY HARD TO CLOSE AND OPEN. THE BEARINGS IN THE DRAWER RAILS SOULND LIKE THEY ARE GRINDING. THE FISRTS PART OF THE RAIL OPENS THEN THE SECONDARY BEARINGS GRIND. Correction:NEED TO REPLACE THE DRAWER ROLLERS IN THE BATHROOM		
3-Authorization number PA03344996				0.60						

r paper claims only use one pre-authorization number per warranty claim for
ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the