

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 1404035 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 4X4TCKC28PX160894 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 017 / 017A <b>ITEM #</b> ACKT274RK <b>DEALER RO #</b> 69736 <b>CLAIM START DATE</b> 01/27/2023 <b>CLAIM END DATE</b> 01/01/1900
<b>Labor rate:</b> \$150.00 <b>OWNER INFORMATION</b>	

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**

<b>Operation Code</b>	<b>Operational Description</b>			
10-11-01-00-000205	Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/No Tread Code			
<b>Complaint, Cause, Correction</b>				
Original Note : bhoffman@americanrvcenter.com, 2023-01-27 11:04:01 :: OFF DOOR SIDE SLIDE OUTSIDE REAR SEAL COMING OFF AND HANGING RIGHT REAR TOP OF SLIDE ROOM IS SUCKING IN BULB SEAL AND WIPER SEAL AND TEARING IT AWAY FROM THE METAL,TOOK BULB SEAL OFF AND PULLED OUT STAPLES AND HAD TO GET GEOSSELL OFF OF METAL AND SEAL,PULLED CHANNEL AND GOT STRAIGHT,GAINED 3/4 OF INCH SO ROOM WOULD NOT HIT IT,RESTAPLED BACK IN PLACE AND SEALED,INSTALLED NEW BULB SEAL,IT WAS TORE UP,TESTED ALL GOOD.				
<b>Model #</b>	<b>Dlr Sub Hrs</b>	2.50	<b>Sub Labor Amt</b>	\$375.00
<b>Serial #</b>	<b>Appr Hrs</b>	1.00	<b>Appr Labor Amt</b>	\$150.00

**Notes**

would this be the same as claim 1336351  
 no if you check the photos on both claims 1336351 is for the top of the slide room and claim 1404035 is for the side of the slide PLEASE SEE PHOTOS THAT ARE ATTACHED IN BOTH CLAIMS  
 Authorized for 1.00 hr.

### Labor

**Line# 2**

<b>Operation Code</b>	<b>Operational Description</b>			
30-101-02-00-001076	Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code			
<b>Complaint, Cause, Correction</b>				
Original Note : bhoffman@americanrvcenter.com, 2023-01-27 11:05:16 :: BATH ROOM DOOR HITS TOOK OFF PLASTIC DOOR FRAME WRAP AND CUT DOWN PANELING OVERHANG AND REINSTALLED PLASTIS WRAP AND DOOR CATCH AND ADJUSTED DOOR KNOB PLUNGER.				
<b>Model #</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$30.00
<b>Serial #</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$30.00

**Notes**

### Labor

**Line# 3**

<b>Operation Code</b>	<b>Operational Description</b>			
30-100-01-00-001042	Mirror or Glass From Cabinet Door Frame - Interior/Cabinetry/Replace/No Tread Code			
<b>Complaint, Cause, Correction</b>				
Original Note : bhoffman@americanrvcenter.com, 2023-01-27 11:13:11 :: CABINETS ABOVE THE FIRE PLACE RUB AND THE GLASS IS CRACKED GLASS IS BROKEN IN CABINET DOOR.NEED NEW GLASS.				
<b>Model #</b>	<b>Dlr Sub Hrs</b>	0.40	<b>Sub Labor Amt</b>	\$60.00
<b>Serial #</b>	<b>Appr Hrs</b>	0.40	<b>Appr Labor Amt</b>	\$60.00

Notes

**Labor**  
**Line# 4**

**Operation Code**  
70-469-01-00-001800

**Operational Description**  
Refrigerator Door - Appliances/Refrigerator (Furrion)/Replace/No Tread Code

**Complaint, Cause, Correction**  
Original Note : bhoffman@americanrvcenter.com, 2023-01-27 11:14:13 :: FRIDGE DOOR WILL NOT SHUT drilled out holes in latch and put different bolts in and had to raise door hinges to catch latch all is good.

<b>Model #</b>	GRF10DBGL	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b>	\$45.00
<b>Serial #</b>	2022071754	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b>	\$45.00

Notes

<b>Submitted</b>	Labor Amt	\$510.00	<b>Approved</b>	Labor Amt	\$285.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$510.00		Total	\$285.00

\_\_\_\_\_  
**DEALER** **DATE**  
**SIGNATURE**  
I certify that I have performed these repairs consistent with Forest River Policies.

\_\_\_\_\_  
**CUSTOMER** **DATE**  
**SIGNATURE**  
All repairs described have been inspected and are satisfactory.