



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69759
Promised Date:
24 AUG 23

CUSTOMER WORK ORDER

WO #: 69759

Customer: 21435 - EDWARDS, JAMES
R. - 812-309-0641

Tag:

Author: PH

Location: 0224 CHECK WORK

Stock #: 11242

Stock Desc: 2023 TT KEYSTONE

COUGAR HALF-TON 30BHS

Chassis #: 4YDTCGP25PL500486

Serial #: 4YDTCGP25PL500486

Mileage: 0

Licence:

Invoice #: 387730

Date In: 30 JAN 23

Promised: 31 AUG 22

Date Sched:

Completed: 22 FEB 23

Warr. Date: 18 AUG 22

Job #ROOFT - Internal

COMPLAINT: INSPECT ROOF AND SEAMS - FILL VOIDS TT/FW

LED LIGHTS IN BATHROOM HAVE HAD WATER IN THEM. SEE IF CAN FIND CAUSE

CAUSE: inspected all seals and entire roof. all vents, skylight, a/c shroud all look good. no signs of damage or leaks.

CORRECTION: no correction.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #ROOFT: 0.00

Job #9 - Internal

COMPLAINT: CHECK CABLES ON SLIDE, CUSTOMER STATES THEY SEEM LOOSE

CAUSE: ran slide room in and out. cables have very little "play" when room is open and closed. this is normal.

CORRECTION: no corrections made at this time. 2/2/23

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: BLACK TANK FLUSH NOT WORKING

CAUSE: black tank check valve is not allowing water to flow through it. removed check valve and the spring and plastic piece from the inside came out of the valve. need to replace.

CORRECTION: secured new check valve to the lines. tested with water hose.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	32.00



Customer #:
21435

W/O: 69759
Promised Date:
31 AUG 22



Customer #:
21435



Parts

Part #	Description	Qty	Price	Total
282770	94239 VACUUM BREAKER/CHECK VALVE	1.00	21.25	21.25

Subtotal for Job #10: 53.25

Job #11 - Internal

COMPLAINT: BATTERIES ARE ONLY READING 1.5V. COULD BE THE BMS NEEDS RESET. HE KEEPS IT PLUGGED IN AT HOME.

CAUSE: PULLED UNIT INTO SHOP AND HOOKED UP TO SHORE POWER. BATTERIES ARE SHOWING 1.7 VOLTS. CONTACTED MANUFACTURE FOR TROUBLE SHOOTING GUIDE. WAS TOLD TO UNHOOK BATTERIES COMPLETELY AND CHARGE WITH REQUIRED CHARGER OR HOOK UP TO A CAR BATTERY WITH THE CAR IDLEING. DISCONNECTED BOTH BATTERIES. TOOK A METER AND TESTED EACH BATTERY. ONE BATTERY TESTED AND 12.5 THE OTHER TESTED AT 8 VOLTS. REMOVED LOWER VOLTAGE BATTERY AND TOOK OF TO BAY. PULLED TRUCK INSIDE AND CHARGER PER INSTRUCTIONS. VOLTAGE DID NOT CHANGE. TOOK A BATTERY CHARGER AND CHARGED OVERNIGHT. LET BATTERY SIT. CHECKED VOLTAGE. VOLTAGE IS STIL AT 8.3 VOLTS. BEN IS CONTACTING WARRANTY. 2/3/23

CORRECTION: warranty replaced both batteries. installed batteries. installed lock. tested system. 12 volt is working as it should.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Subtotal for Job #11: 0.00

Parts Total: 21.25
Labour Total: 32.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 53.25

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Feb 2023

