

Pre-Authorization

2/15/20
10:05:55

Pre-Authorization number PA03363389 Reference no: 69791 Status: Approved Approved by steic Approved date 2/6/2023
Customer Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTSGN23N3107119
600 E Baseline Rd
Evansville, IN 47725

Job Root operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3300516A Blind - Vertical - F	0.00	0.10	0.10		1	0.20	Complaint:BARREL THAT HOLDS STRING ON BLIND IN UPPER BUNK IS PULLED OUT OF PANELING Cause:BARREL THAT HOLDS STRING ON BLINDS CAME LOSE ON UBER BUNK. REATTACHED A LITTLE LOWE AND FILLED IN THE OLD HOLE Correction:BARREL THAT HOLDS STRING ON BLINDS CAME LOSE ON UBER BUNK. REATTACHED A LITTLE LOWE AND FILLED IN THE OLD HOLE
2	3100325B Base Cabinets - S	0.00	10.00	10.00		1	0.50	Complaint:CABINET STILE VINEAR. PAPER BUBBLED OVER REFER Cause:FOUND SEVERAL SPOTS WEHERE VINER PAPER WAS PEALING AWAY. HAD SOME AT THE BOTTOM OM OF KITCHEN CABINET NEAR BEDROOM. BOTTOM OF BATHROOM SINK. INSIDE CABINET DOOR, FOUND SOME BY BEDROOM NON DOOR SIDE CABNIET. FOUND WHERE IT WAS PEALING AWAY AT BATHROOM DOOR. Correction:FOUND SEVERAL SPOTS WEHERE VINER PAPER WAS PEALING AWAY. HAD SOME AT THE BOTTOM OM OF KITCHEN CABINET NEAR BEDROOM. BOTTOM OF BATHROOM SINK. INSIDE CABINET DOOR, FOUND SOME BY BEDROOM NON DOOR SIDE CABNIET. FOUND WHERE IT WAS PEALING AWAY AT BATHROOM DOOR.
3	3200108A Door - Interior Hin	0.00	1.00	0.20		1	0.20	KRV - Our laminate stile supplier has released a video showing how the stile repairs can be performed. Please review and if you have any questions please let us know. GENESIS REPAIR VIDEO https://www.youtube.com/watch?v=WGc0lfntTzY KRV - VCB Complaint:BATHROOM DOOR HAS SCRATCHES IN IT Cause:BATHROOM DOOR HAS TEARS NEAR HANDLE. NEED APPROVAL FOR NEW BATHROOM DOOR 72/38 IN HEIGHT

For paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

Pre-Authorization

2/15/20
10:05:55

Job Root or operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
								WIDTH 2FT Correction: PULL CAMPER IN BAY OPEN UP AND REMOVE DOOR AND REMOVE HANDLE AND REINSTALL DOOR AND HANDLE
4	2104115B Slide Out - Box - f	0.00	0.40	0.20		1	0.20	KRV - Approved to fill/blend as needed. Complaint: SLIDEROOM SEALS NEED SILICONED Cause: SLIDEROOM SEALE NEEDED SEALED UP. SEALED UP SLIDE ROOM Correction: SLIDEROOM SEALE NEEDED SEALED UP. SEALED UP SLIDE ROOM
Pre-Authorization number PA03363389				10.50				

For paper claims only use one pre-authorization number per warranty claim for
 include a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the