

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 69803  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 11116 - 2023 CATALINA SUMMIT SERIES 271DBS 5ZT2CASB0PU041637  
VIN: 5ZT2CASB0PU041637 HIN: SER#: 5ZT2CASB0PU041637  
Mileage: 0 Work Order Comp: 21 FEB 23  
Auth. No: Dealer #:  
Warr. Date: Work Order Date: 06 FEB 23 Inv #: 387704

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
69803 3 BATHROOM SHOWER NEEDS SEALED  
bathroom shower surround needed sealed up especially up top thre  
was huge open gap. sealed up shower surround and gap  
bathroom shower surround needed sealed up especially up top thre  
was huge open gap. sealed up shower surround and gap  
  
69803 5 TEAR IN THE WOOD NEAR THE FRIDGE  
replace stile  
pulled out fridge. removed screws from stile. removed stile. cut  
new stile to length. installed new stile. secured stile with  
screws. secured fridge. cleaned up mess.  
  
69803 1 SEALANT ALL OVER HOOK UP COVER  
ther was sealant all over hook up cover from factory. had scrap  
off and use adhesive remover to remove. removed all the sealnt on  
the cover  
ther was sealant all over hook up cover from factory. had scrap  
off and use adhesive remover to remove. removed all the sealnt on  
the cover  
  
69803 2 CABINETS MISSING SCREWS IN THE HINDGES  
CABNIETS WERE MISSING SCREWS FROM FACTORY THE HOLES WER NEVER  
EVEN DRILLED IN HINGES AND WAS ONLY BEING HELD BY ONE SCREW. THE  
ONE BY THE REAR BUNK AND THE OUTSIDE KITCHEN ONE NEEDED SCREWS.  
DRILLED HOLES AND INSATLLED SCREWS  
CABNIETS WERE MISSING SCREWS FROM FACTORY THE HOLES WER NEVER

Claim : 69803

\*\*\*\*\*  
 WO # Job # Description JOB INFORMATION  
 \*\*\*\*\*

EVEN DRILLED IN HINGES AND WAS ONLY BEING HELD BY ONE SCREW. THE ONE BY THE REAR BUNK AND THE OUTSIDE KITCHEN ONE NEEDED SCREWS. DRILLED HOLES AND INSATLLED SCREWS

69803 4 CONVERTER DOOR JAMMED  
 CONVERTER DOOR WAS JAMED DUE TO SCREWS BEING PUT IN AT A ANGLE AND TO TIGHT. ADJUSTED SCREWS AND IT WORKED FINE  
 CONVERTER DOOR WAS JAMED DUE TO SCREWS BEING PUT IN AT A ANGLE AND TO TIGHT. ADJUSTED SCREWS AND IT WORKED FINE

69803 6 EXCESS SEALANT ON ENTRY DOOR HANDLES ON BOTH DOORS  
 there was excess sealant from factory on entry door handles that needed cleaned up. had to scrape off and use adhesive remover to remove  
 there was excess sealant from factory on entry door handles that needed cleaned up. had to scrape off and use adhesive remover to remove

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
APP017-412406	3	CLEAR SIKASIL PLUS		1.00	17.86	17.86
F100285188	5	3" CABINET STILE		1.00	1.38	1.38

\*\*\*\*\*

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.30	160.00	48.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		3.00	160.00	480.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.30	160.00	48.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00

\*\*\*\*\*

\*\*\*\*\*

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	5	FREIGHT		1.00	31.59	31.59

\*\*\*\*\*

Parts Total: 19.24  
 Labour Total: 672.00  
 Sublet Total: 0.00  
 Extras Total: 31.59

>>>> Claim Total: 722.83

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_