

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69866
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 10738 - 2023 SPRINGDALE 2010BH 4YDTSUGH22PW102216

VIN: 4YDTSUGH22PW102216 HIN: SER#: 4YDTSUGH22PW102216

Mileage: 0 Work Order Comp: 31 MAR 23

Auth. No: Dealer #: 1194

Warr. Date: Work Order Date: 17 FEB 23 Inv #: 389466

WO # Job # Description JOB INFORMATION

69866 9 BLACK TANK DUMP VALVE NOT CLOSING
BKACK DUMP VALVE NOT CLOSING.
Checked black dump valve. Slide groove had pipe glue in it.
Glue will not come out. Removed damaged black tank dump valve.
Installed new dump valveand seals. Checked for leaks. OK.

69866 15 SCRATCH IN PAINT ON REAR METAL BY SPRINGDALE LOGO
FOUND METAL DAMAGED WILL HAVE TO PULL BOTH SIDE CORNERS OFF PULL
WINDOW OUT PULL METAL OFF AND INSTALL NEW METAL INSTALL WINDOW
AND THE DECALS THAT COME WITH IT
REMOVE CORNERS. REMOVE WINDOW. REMOVE DAMAGED SIDING. INSTALL NEW
SIDING. PUT BACK WINDOWS AND CORNERS. PUT ON DECALS AND
SILICONED.

69866 6 BATHROOM DOOR RUBS WHEN OPENING
BATHROOM DOOR RUBS WHEN OPENING.
Checked operation of bathroom door. Added screws to door jamb to
secure to door frame.

69866 12 SCRATCH IN WOOD PANEL ABOVE THE FRIDGE
there is a scartch aboe fridge marked with tape that needs fixed
needs seam tape over it

69866 13 SCRATCH UNDER THER REAR BUNK
scratches under bunk need fixed
needs seam tape over it

Claim : 69866

```

*****
WO #      Job #      Description      JOB INFORMATION
*****

```

```

69866      14      TRIM BY REAR DOOR INSIDE LOOSE
           trim by rear door has come lose from staples
           needs to be restapled back on

```

```

*****
Part No    Job#    Description      PARTS      Qty      Price      Total
*****
VLPT1003VPM  9      3" WASTE VALVE      1.00      14.50      14.50
696980      15      Diecut - 2023 - SG - Side/Rear - 1.00      11.71      11.71
696981      15      Diecut - 2023 - SG - Side/Rear - 1.00      4.37      4.37
273206      15      18" X 96" WHITE S-LOCK 1.00      28.93      28.93

```

```

*****
Lab Code   Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      9      MISCELLANEOUS REPAIR      0.60      150.00      90.00
Z990      15     MISCELLANEOUS REPAIR      4.18      160.00      668.80
Z990      15     MISCELLANEOUS REPAIR      0.32      160.00      51.20
Z990      6      MISCELLANEOUS REPAIR      0.20      150.00      30.00
Z990      12     MISCELLANEOUS REPAIR      0.00      160.00      0.00
Z990      12     MISCELLANEOUS REPAIR      0.20      160.00      32.00
Z990      13     MISCELLANEOUS REPAIR      0.00      160.00      0.00
Z990      13     MISCELLANEOUS REPAIR      0.20      160.00      32.00
Z990      14     MISCELLANEOUS REPAIR      0.00      160.00      0.00
Z990      14     MISCELLANEOUS REPAIR      0.10      160.00      16.00

```

```

*****
Excode    Job#    Description      EXTRAS      Qty      Price      Total
*****
FRT       15     UPS - METAL & DECALS      1.00      155.32      155.32

```

```

Parts Total:      59.51
Labour Total:     920.00
Sublet Total:     0.00
Extras Total:     155.32

```

>>>> Claim Total: 1,134.83

Customer Signature: _____

Date: _____