

e-Authorization

2/21/20
10:02:54

3-Authorization number PA03372795 Reference no: 69871 Status: Approved Approved by samya Approved date 2/20/2023
rving Name Address VIN Retail sold on

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFCGN27N2500301	10/29/2021
----	----------------------	---	-------------------	------------

lu Root e operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2102314A Wall - Hung Glass	0.00	3.00	3.00		1	0.30	Complaint:THE WINDOW BEHIND THE KITCHEN FAUCET IS NOT INSTALLED PROPERLY. THE LEFT SIDE AND THE BOTTOM OF THE FRAME APPEAR TO BE IN A BIND. DAYLIGHT CAN BE SEEN THROUGH THE LOWER LEFT CORNER OF THE WINDOW FRAME. Cause:after removing the window. we found the two back walls are not square with each other. Correction:helped brett removed excess material on one side of the window. cleaned up silicone around window. installed window. siliconed around outside of window. CUT WINDOW TO FIT PROPERLY. THAN INSTALLED IT BACK. SILICONE INSIDE TO SEAL BETTER. PUT BLIND UP AND VALANCE

3-Authorization number PA03372795 3.00

r paper claims only use one pre-authorization number per warranty claim for
ple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the