

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 1439066 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 5ZT2CANB2PU041053 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 103 / 103 <b>ITEM #</b> CAT243RBSLE <b>DEALER RO #</b> 69876 <b>CLAIM START DATE</b> 02/27/2023 <b>CLAIM END DATE</b> 01/01/1900
<b>Labor rate:</b> \$160.00 <b>OWNER INFORMATION</b>	

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

**Labor**  
Line# 1

<b>Operation Code</b>	<b>Operational Description</b>		
22-615-16-24-000617	Roof Rack or Ladder, each - Cargo Exterior/Exterior Miscellaneous/Structure/Repair		
<b>Complaint, Cause, Correction</b>			
Original Note : bhoffman@americanrvcenter.com, 2023-02-27 10:10:46 :: ON THE BACK RACK THE HOLE IS NOT BIG ENOUGH FOR THE PIN DRILLED OUT HOLE WITH BIGGER BIT,FIT PIN ,ALL IS GOOD.			
<b>Model #</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>	<b>\$48.00</b>
<b>Serial #</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>	<b>\$48.00</b>

**Notes**

**Labor**  
Line# 2

<b>Operation Code</b>	<b>Operational Description</b>		
23-535-00-15-003557	Skirt - Bus Exterior/Skirting/No Tread Code/Repair or Replace		
<b>Complaint, Cause, Correction</b>			
Original Note : bhoffman@americanrvcenter.com, 2023-02-27 10:12:44 :: STRAP ON THE OFF DOOR SIDE REAR FROM THE FRAME TO THE J WRAP IS NOT CONNECTED BENT STRAP IN PLACE FOR SKIRT AND SCREWED TO STRAP.			
<b>Model #</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>	<b>\$16.00</b>
<b>Serial #</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>	<b>\$16.00</b>

**Notes**

AUTHORIZED AS REQUESTED

**Labor**  
Line# 3

<b>Operation Code</b>	<b>Operational Description</b>		
30-101-02-00-001077	Hinged Passage Door Striker - Interior/Interior Doors/Adjust/No Tread Code		
<b>Complaint, Cause, Correction</b>			
Original Note : bhoffman@americanrvcenter.com, 2023-02-27 10:14:00 :: BEDROOM DOOR WONT LATCH TOOK OFF CATCH AND CUT HOLE BIGGER IT WAS WAY OFF,INSTALLED CATCH AND ALL GOOD.			
<b>Model #</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>	<b>\$32.00</b>
<b>Serial #</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>	<b>\$16.00</b>

**Notes**

EXcessive amount requested. Adjusted to flat rate

**Labor**  
Line# 4

<b>Operation Code</b>	<b>Operational Description</b>		
30-101-02-00-001077	Hinged Passage Door Striker - Interior/Interior Doors/Adjust/No Tread Code		
<b>Complaint, Cause, Correction</b>			

