



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69895
Promised Date:
28 FEB 23



Customer #:
1000



CUSTOMER WORK ORDER

WO #: 69895
Customer: 1000 - BASDEN'S
AMERICAN RV -
Tag:
Author: BH
Location: 0302 CHECK PREAUTH

Stock #: 10630
Stock Desc: 2023 TT COACHMEN
CATALINA 343BHTSLE
Chassis #: 5ZT2CAZB4PX028622
Serial #: 5ZT2CAZB4PX028622
Mileage:
Licence:

Invoice #:
Date In: 21 FEB 23
Promised: 28 FEB 23
Date Sched:
Completed: 28 FEB 23
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT - PDI NEW TRAVEL TRAILER.

CORRECTION: Moved unit into shop from sales lot. Installed battery box. Cut battery cables to fit. Filled LP tanks. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Applied all company decals. Checked roof and awning. Checked all stab jacks. Checked power cord. Checked converter output. Checked entrance door and all compartment doors. Checked all interior lights. Checked all electrical outlets and GFCI outlets. Checked all cabinets and drawers. Checked all windows and blinds. Took pictures and recorded all serial numbers. Added water to freshwater tank and flushed antifreeze from water lines. Checked all water lines and faucets for leaks. Opened by-pass on water heater and filled. Purged all air from system. Performed LP drop test and set LP pressure at 10 1/2 in.wc. Filled all holding tanks and checked monitor panel. Dumped all holding tanks, including water heater. Retracted all stab jacks. Moved unit back to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: WINTER - WINTERIZE UNIT AND DRAIN HOLDING TANKS.***INCLUDES 2 GALLONS
ANTIFREEZE.





CORRECTION: By-passed water heater. Blew out all water lines and faucets. Added antifreeze to all water lines and faucets, including outside kitchen and outside shower. Poured antifreeze in all drain traps including outside sink drain. Drained all holding tanks, including water heater.

Labor			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DKM	N/C
Z990	WINTERIZE UNIT	DKM	N/C

Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: TEST TV WONT PICK UP CHANNELS

CAUSE: TEST TV WONT PICK UP CHANNELS.

CORRECTION: Checked all cables for correct location on back of booster. Checked to see if all cables are good. Cable on roof TV antenna had insulator over center coax preventing it from making contact with antenna terminal. Ran channel scan again and TV picked up channels. Outside coax locations were labeled wrong. Added label to cable location on roadside. Changed label on curbside to read only Sattelite instead of Cable/Sattelite. Remounted booster beck in wall.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	121.60
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	41.60
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	12.80

Subtotal for Job #1: 176.00

Job #2 - Warranty

COMPLAINT: ENTRY AND SCREEN DOOR NEED ADJUSTED. NOTED ON DELIVERY

CAUSE: ENTRY DOOR AND SCREEN DOOR NEED ADJUSTED. NOTED ON DELIVERY.

CORRECTION: Screen door is hard to close and latch. Entry door has to be slammed to latch closed, then it is hard to open. Adjusted hinges on screen door to allow it to close and stay closed. Adjusted entry door latch. Ground door frame behind latch plate to allow more adjustment. Entry door now easier to close and latch.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	48.00

Subtotal for Job #2: 48.00

Job #3 - Warranty

COMPLAINT: TRIM LOOSE ON INSIDE OF ENTRY DOOR. NOTED ON DELIVERY

CAUSE: TRIM LOOSE ON INSIDE OF ENTRY DOOR. NOTED ON DELIVERY.

CORRECTION: Trim next to entry door on the inside is loose and not secured to wall. Reattached trim with brad nails. Filled all holes with matching putty.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	32.00



W/O: 69895
Promised Date:
28 FEB 23



Subtotal for Job #3: 32.00

Parts Total: 0.00

Labour Total: 256.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 256.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 28 Feb 2023

Customer Signature : _____

Customer #:
1000

