

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1449432
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKY29PK085838
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	094 / 094A
Labor rate:	\$160.00	ITEM #	CKT23MKBL-94
OWNER INFORMATION		DEALER RO #	69907
		CLAIM START DATE	03/07/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase	WARRANTY EXPIRATION DATE
-------------------------	--------------------------

Claim Line Details

Labor				
Line# 1	Operation Code	Operational Description		
	10-11-01-00-000205	Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-03-07 13:11:45 :: SEAL UNDER SLIDE COMING OFF SEAL UNDER SLIDE IS COMING OFF THE SCREWS HOLDING IT FELL OUT. REMOVED OLD SEALANT WHICH WAS STUCK ON THERE PRETTY GOODAND SLID SEAL BACK ON AND INSTALLED TWO NEW BLACK SELFTAPPING SCREWS TO HOLD IT IN PLACE. ONCE SECURED I RESEALED AROUND THE SEAL SEAL UNDER SLIDE IS COMING OFF THE SCREWS HOLDING IT FELL OUT. REMOVED OLD SEALANT WHICH WAS STUCK ON THERE PRETTY GOODAND SLID SEAL BACK ON AND INSTALLED TWO NEW BLACK SELFTAPPING SCREWS TO HOLD IT IN PLACE. ONCE SECURED I RESEALED AROUND THE SEAL			
	Model #	Dlr Sub Hrs	0.70	Sub Labor Amt \$112.00
	Serial #	Appr Hrs	0.00	Appr Labor Amt \$0.00

Notes
Denied. This repair was authorized and paid in claim 1341937.

Labor				
Line# 2	Operation Code	Operational Description		
	30-99-01-00-001018	Day Night Shade or Roller Shade - Interior/Soft Goods/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-03-07 13:12:47 :: ZEBRA SLIDE BLIND NOT WORKING ZEBRA SLIFDE BLINDS NOT WORKING RIGHT. ON FURTHER UINSPECTION I FOUND FABRIC WAS TORE AND MAIN METAL BEAM WAS BENT CASUING IT NOT TO GO UP AND DOWN PROPERLEY. NEEDS NEW ONE INSTALLED ZEBRA SLIFDE BLINDS NOT WORKING RIGHT. ON FURTHER UINSPECTION I FOUND FABRIC WAS TORE AND MAIN METAL BEAM WAS BENT CASUING IT NOT TO GO UP AND DOWN PROPERLEY. NEEDS NEW ONE INSTALLED			
	Model #	Dlr Sub Hrs	0.30	Sub Labor Amt \$48.00
	Serial #	Appr Hrs	0.20	Appr Labor Amt \$32.00

Notes
Authorized for flatrate of 0.20 hrs.

Labor				
Line# 3	Operation Code	Operational Description		
	20-66-02-00-000664	Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-03-07 13:14:12 :: ENRTY DOOR RUBS ENTRY DOOR WAS HIITING STRIKING PLATE CASUING IT TO RUB. ADJUSTED STRIKING PLATE AND TESTTED DOOR WHICH FIXED THE PROBLEM ENTRY DOOR WAS HIITING STRIKING PLATE CASUING IT TO RUB. ADJUSTED STRIKING PLATE AND TESTTED DOOR WHICH FIXED THE PROBLEM			
	Model #	Dlr Sub Hrs	0.30	Sub Labor Amt \$48.00

Serial #
Notes

Appr Hrs

0.30

Appr Labor Amt \$48.00

Submitted

Labor Amt	\$208.00
Parts & Freight	\$0.00
Total	\$208.00

Approved

Labor Amt	\$80.00
Parts & Freight	\$0.00
Total	\$80.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.