

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1437005
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKT27PK085831
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT18RRBL-94
		DEALER RO #	69908
		CLAIM START DATE	02/24/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-102-01-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Replace/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-02-24 08:38:28 :: CORNER TRIM NEAR BED DAMAGED took picture of damaged corner trim then wait on warranty to approve. FILED OUT PO SHEET FOR BEN. NEED A NEW BATON STRIP. PULL OLD TRIM OFF AND INGSTALL NEW TRIM	
	Model #	Dlr Sub Hrs 0.20 Sub Labor Amt \$32.00
	Serial #	Appr Hrs 0.20 Appr Labor Amt \$32.00

Notes

Labor

Line# 2	Operation Code 30-101-02-00-001076	Operational Description Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-02-24 08:40:14 :: BATHROOM DOOR RUBS TOOK PICTURES OF DOOR AND TRIMED OUT. OPENED THE BATHROOM DOOR THEN REMOVED THE SCREWS AT THE STRIKER PLATE AND DOOR MOLDING. PULLED PANELING BACK WITH TOOLS AND REMOVED THE STAPLES. USED A HAMMER TO KNOCK BACK THE STUD AN 1/8 INCH. TRIMED THE EXTRA WOOD FOR DOOR CLEARANCE. RESTAPLED THE PANEL TO THE WALL THEN PUT SCREWS BACK IN DOOR MOLDING AND STRIKER PLATE. CHECKED THE DOOR FOR PROPER LATCHING. NO OTHER ISSUES WITH BATHROOM DOOR.	
	Model #	Dlr Sub Hrs 0.60 Sub Labor Amt \$96.00
	Serial #	Appr Hrs 0.60 Appr Labor Amt \$96.00

Notes

Authorized as requested.

Labor

Line# 3	Operation Code 30-100-02-00-003062	Operational Description Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-02-24 08:41:29 :: ABOVE KITCHEN SINK CABINET RUBS TOOK PICTURES OF HOW TIGHT THE DOORS ARE. USED A PIECE OF CARDBOARD TO PUSH DOORS APART. NOW DOORS SHUT WITH EASE,THERE IS ABOUT 1/16 GAP BETWEEN DOORS.	
	Model #	Dlr Sub Hrs 0.40 Sub Labor Amt \$64.00
	Serial #	Appr Hrs 0.20 Appr Labor Amt \$32.00

Notes

Labor
Line# 4

Authorized for 0.20 hrs. 0.40 hrs appears excessive.

Operation Code 30-99-01-00-001016	Operational Description Mini-Blind Hold Down Bracket - Interior/Soft Goods/Replace/No Tread Code
---	--

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-02-24 08:42:31 :: ABOVE KITCHEN SINK SHADE HOLDER BROKEN took picture of damaged shade holder will replace with new part. PULLED BLINDS UP THEN REMOVED THE SCREWS THAT HOLD THE HOLDER TO WALL.REPLACED BOTH DUE TO COLOR. DAMAGED HOLDER WAS A CLEAR WHITE AND NEW HOLDERS ARE CLEAR. THEN CLIPPED IN BLIND TO HOLDER.

Model #	Dir Sub Hrs	0.10	Sub Labor Amt	\$16.00
Serial #	Appr Hrs	0.10	Appr Labor Amt	\$16.00

Notes
Authorized as requested.

Submitted	Labor Amt	\$208.00	Approved	Labor Amt	\$176.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$208.00		Total	\$176.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.