



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69908
Promised Date:
28 FEB 23



Customer #:
1000



CUSTOMER WORK ORDER

WO #: 69908

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: BH

Location: 0303 CHECK STATUS WITH
SAR

Stock #: 10796

Stock Desc: 2023 TT FOREST RIVER
CHEROKEE GREY WOLF 18RRBL

Chassis #: 4X4TCKT27PK085831

Serial #: 4X4TCKT27PK085831

Mileage: 0

Licence:

Invoice #:

Date In: 23 FEB 23

Promised: 28 FEB 23

Date Sched:

Completed: 28 FEB 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: CORNER TRIM NEAR BED DAMAGED

CORRECTION: took picture of damaged corner trim then wait on warranty to approve. FILED OUT PO SHEET FOR BEN. NEED A NEW BATON STRIP.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
F100213775	BATTEN, 7/8" X 7' - NIRVANA FROST (SET OF 10)	1.00	29.74	29.74

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-BATTEN	1.00	31.55	31.55

Subtotal for Job #1: 93.29

Job #2 - Warranty

COMPLAINT: BATHROOM DOOR RUBS

CORRECTION: TOOK PICTURES OF DOOR AND TRIMED OUT. OPENED THE BATHROOM DOOR THEN REMOVED THE SCREWS AT THE STRIKER PLATE AND DOOR MOLDING. PULLED PANELING BACK WITH TOOLS AND REMOVED THE STAPLES. USED A HAMMER TO KNOCK BACK THE STUD AN 1/8 INCH. TRIMED THE EXTRA WOOD FOR DOOR CLEARANCE. RESTAPLED THE PANEL TO THE WALL THEN PUT SCREWS BACK IN DOOR MOLDING AND STRIKER PLATE. CHECKED THE DOOR FOR PROPER LATCHING. NO OTHER ISSUES WITH BATHROOM DOOR.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	96.00

Subtotal for Job #2: 96.00

Job #3 - Warranty

COMPLAINT: ABOVE KITCHEN SINK CABINET RUBS

CORRECTION: TOOK PICTURES OF HOW TIGHT THE DOORS ARE. USED A PIECE OF CARDBOARD TO PUSH DOORS APART. NOW DOORS SHUT WITH EASE, THERE IS ABOUT 1/16 GAP BETWEEN



DOORS.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	32.00

Subtotal for Job #3: 32.00

Job #4 - Warranty

COMPLAINT: ABOVE KITCHEN SINK SHADE HOLDER BROKEN

CORRECTION: took picture of damaged shade holder will replace with new part. PULLED BLINDS UP THEN REMOVED THE SCREWS THAT HOLD THE HOLDER TO WALL.REPLACED BOTH DUE TO COLOR. DAMAGED HOLDER WAS A CLEAR WHITE AND NEW HOLDERS ARE CLEAR. THEN CLIPPED IN BLIND TO HOLDER.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	16.00

Parts

Part #	Description	Qty	Price	Total
A301	A301 MINI BLIND HOLD-DOWN HOOK	1.00	2.19	2.19

Subtotal for Job #4: 18.19

Parts Total: 31.93

Labour Total: 176.00

Sublet Total: 0.00

Extras Total: 31.55

WORK ORDER TOTAL: 239.48

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Mar 2023

W/O: 69908
Promised Date:
28 FEB 23

Customer #:
1000

