

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

Labor rate: \$160.00

OWNER INFORMATION

CLAIM STATUS Authorized
CLAIM 1456663
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CARB5PX027530
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 205 / 205
ITEM # ACAT263FKDSLE
DEALER RO # 69916
CLAIM START DATE 03/13/2023
CLAIM END DATE 01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code
20-69-02-00-000705

Operational Description
Compartment Door - Exterior/Compartment Doors/Adjust/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-13 17:04:59 :: DOOR SIDE FRONT COMPARTMENT THERE IS WATER door side front compartment there is wtaer damage because of door not being sealed. TOOK WOOD GRAIN TAPE AND COVERD STAIN. SILICONED AROUND DOOR

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes

Labor

Line# 2

Operation Code
01-20-501-003385

Operational Description
Trim - Vinyl - Replace/Exterior/Park Model Siding

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-13 17:06:14 :: RIGHT OF THE KITCHEN SINK HOLE IN THE WALL RIGHT OF THE KITCHEN HAS HOLE NEAR SINK NEEDS WALL REPLACED OR FIXED STAPLE BATON STRIP ON WALL AND COVERED STAPLE HOLES

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes

AUTHORIZED AS REQUESTED.

Labor

Line# 3

Operation Code
01-30-102-001117

Operational Description
Trim Molding, each - Replace/Interior/Panels, Ceilings, & Interior Moldings

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-13 17:07:37 :: WALL PAPER ABOVE BATHDOOR COMING OFF NEDED SMOOTHED BACK ON WALL PAPER ABOVE BATHDOOR COMING OFF NEDED SMOOTHED BACK ON IT JUST WAS HANGING OFF A BIT

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes

PHOTOS DO NOT MATCH JOB DESCRIPTION.
Sorry the correct photos are added
AUTHORIZED AS REQUESTED

Labor

Line# 4

Operation Code

02-30-101-001076

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-03-13 17:08:34 :: BATH TO BED DOOR RUBS BATH TO DOOR RUBBING AGAINST STRIKING PLATE CAUSING DOOR NOT TO SHUT PROOPERLEY. ADJUSTED STRIKING PLATE BATH TO DOOR RUBBING AGAINST STRIKING PLATE CAUSING DOOR NOT TO SHUT PROOPERLEY. ADJUSTED STRIKING PLATE

Operational Description

Hinged Passage Door - Adjust/Interior/Interior Doors

Model #

Serial #

Dlr Sub Hrs

Appr Hrs

0.20

0.20

Sub Labor Amt

Appr Labor Amt

\$32.00

\$32.00

Notes

Authorized as requested

Submitted	Labor Amt	\$128.00	Approved	Labor Amt	\$128.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$128.00		Total	\$128.00

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.