



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69916
Promised Date:
28 FEB 23



Customer #:
1000



CUSTOMER WORK ORDER

WO #: 69916

Customer: 1000 - BASDEN'S

AMERICAN RV -

Tag:

Author: BH

Location: 0321 CHECK STATUS WITH
BB

Stock #: 11118

Stock Desc: 2023 TT COACHMEN

CATALINA 263FKDSLE

Chassis #: 5ZT2CARB5PX027530

Serial #: 5ZT2CARB5PX027530

Mileage: 0

Licence:

Invoice #:

Date In: 23 FEB 23

Promised: 28 FEB 23

Date Sched:

Completed: 17 MAR 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: DOOR SIDE FRONT COMPARTMENT THERE IS WATER

CAUSE: door side front compartment there is wtaer damage because of door not being sealed. have bret look at it

CORRECTION: door side front compartment there is wtaer damage because of door not being sealed. have bret look at it

TOOK WOOD GRAIN TAPE AND COVERD STAIN. SILICONED AROUND DOOR

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

Parts

Part #	Description	Qty	Price	Total
F100285217	TAPE, SEAM VINYL 6" - 150' ROLL - CHILI TEAK 457147 MC 2022	10.00	0.90	9.00

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SEAM TAPE	1.00	15.84	15.84

Subtotal for Job #1: 56.84

Job #2 - Internal

COMPLAINT: FOUND WATER RUST NEAR STOVE

CAUSE: FOUND WATER RUST ABOVE STOVE COMIING FROM ROOF

CORRECTION: cleaned area

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #2: 0.00





Job #3 - Warranty

COMPLAINT: RIGHT OF THE KITCHEN SINK HOLE IN THE WALL

CAUSE: RIGHT OF THE KITCHEN HAS HOLE NEAR SINK NEEDS WALL REPLACED OR FIXED

CORRECTION: STAPLE BATON STRIP ON WALL AND COVERED STAPLE HOLES

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	32.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

Parts

Part #	Description	Qty	Price	Total
F100130672	7/8" BATTEN VIPER TRUFFLE	1.00	1.86	1.86

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-BATTEN STRIP	1.00	28.06	28.06

Subtotal for Job #3: 61.92

Job #4 - Warranty

COMPLAINT: WALL PAPER ABOVE BATHDOOR COMING OFF NEEDED SMOOTHED BACK ON

CAUSE: WALL PAPER ABOVE BATHDOOR COMING OFF NEEDED SMOOTHED BACK ON IT JUST WAS HANGING OFF A BIT

CORRECTION: WALL PAPER ABOVE BATHDOOR COMING OFF NEEDED SMOOTHED BACK ON IT JUST WAS HANGING OFF A BIT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

Subtotal for Job #4: 32.00

Job #5 - Warranty

COMPLAINT: BATH TO BED DOOR RUBS

CAUSE: BATH TO DOOR RUBBING AGAINST STRIKING PLATE CAUSING DOOR NOT TO SHUT PROPERLY. ADJUSTED STRIKING PLATE

CORRECTION: BATH TO DOOR RUBBING AGAINST STRIKING PLATE CAUSING DOOR NOT TO SHUT PROPERLY. ADJUSTED STRIKING PLATE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

Subtotal for Job #5: 32.00

Parts Total: 10.86
 Labour Total: 128.00
 Sublet Total: 0.00
 Extras Total: 43.90

WORK ORDER TOTAL: 182.76

