

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1459680
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAXB4PX027263
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT323BHDSCKLE
		DEALER RO #	69921
		CLAIM START DATE	03/15/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 01-20-66-000674 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-03-15 14:45:55 :: SEAL ON ENTRY DOOR SEAL ON ENTRY DOOR HAD COME LOOSE BECAUSE OF ADHESIVE REMOVED OLD ADHESIVE AND INSTALLED ADHESIVE SEAL ON ENTRY DOOR HAD COME LOOSE BECAUSE OF ADHESIVE REMOVED OLD ADHESIVE AND INSTALLED ADHESIVE	Operational Description Entry Door Weather Stripping - Replace/Exterior/Entry Doors	
	Model # Serial #	Dlr Sub Hrs Appr Hrs	Sub Labor Amt \$32.00 Appr Labor Amt \$32.00
	Notes auTHORIZED AS REQUESTED		

Labor

Line# 2	Operation Code 01-30-102-001117 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-03-15 14:46:38 :: FRIDGE DOOR IS HARD TO SHUT DUE TO THE WOOD ON THE BOTTOM FRIDGE DOOR WAS HARD TO SHUT DUE TO WOOD SUPPORT TO HIGH UP. REMOVED SCREWS AND LOWERED WOOD. REINSTALLED SCREWS AND TESTED DOOR FRIDGE DOOR WAS HARD TO SHUT DUE TO WOOD SUPPORT TO HIGH UP. REMOVED SCREWS AND LOWERED WOOD. REINSTALLED SCREWS AND TESTED DOOR	Operational Description Trim Molding, each - Replace/Interior/Panels, Ceilings, & Interior Moldings	
	Model # Serial #	Dlr Sub Hrs Appr Hrs	Sub Labor Amt \$32.00 Appr Labor Amt \$32.00
	Notes AUTHORIZED AS REQUESTED		

Labor

Line# 3	Operation Code 01-60-136-001500 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-03-15 14:48:11 :: UNDER SINK AND STOVE THE WATER IS WET SUNDER SINK AND STOVE WAS WET DUE TO A LOSE CONNECTION ON FITTING. TIGHTENED FITTING SUNDER SINK AND STOVE WAS WET DUE TO A LOSE CONNECTION ON FITTING. TIGHTENED FITTING	Operational Description Fitting - Replace/Plumbing/Fresh Water Supply	
	Model # Serial #	Dlr Sub Hrs Appr Hrs	Sub Labor Amt \$16.00 Appr Labor Amt \$16.00
	Notes AUTHORIZED AS REQUESTED		

Submitted	Labor Amt	\$80.00
	Parts & Freight	\$0.00
	Total	\$80.00

Approved	Labor Amt	\$80.00
	Parts & Freight	\$0.00
	Total	\$80.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	