



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69928
Promised Date:
28 FEB 23

CUSTOMER WORK ORDER

WO #: 69928

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: BH

Location: 0315 CHECK PREEAUTH

Stock #: 10760

Stock Desc: 2023 TT COACHMEN
FREEDOM EXPRESS 259FKDS

Chassis #: 5ZT2FERB3PW026302

Serial #: 5ZT2FERB3PW026302

Mileage: 0

Licence:

Invoice #:

Date In: 24 FEB 23

Promised: 28 FEB 23

Date Sched:

Completed: 09 MAR 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: DINNETTE CABINET WONT REACH

CAUSE: DINEETTE CABNIET WONT REACH AS HINGES WERE LOSSE AND LATCHES NOT IN PROPER SPOTS. REMOVED SCREWS AND ATTACHED LONGER SCREWS INSTEAD OF THE SHORT ONES THAT WERE ORIGINALLY ATTACHED. THEN MOVED UP LATCH SO THAT IT WOULD LATCH PROPERLY AND THEN TESTED DOOR.

CORRECTION: DINEETTE CABNIET WONT REACH AS HINGES WERE LOSSE AND LATCHES NOT IN PROPER SPOTS. REMOVED SCREWS AND ATTACHED LONGER SCREWS INSTEAD OF THE SHORT ONES THAT WERE ORIGINALLY ATTACHED. THEN MOVED UP LATCH SO THAT IT WOULD LATCH PROPERLY AND THEN TESTED DOOR.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

Subtotal for Job #1: 32.00

Job #2 - Warranty

COMPLAINT: KITCHEN CLOSET DOOR RUBS

CAUSE: KITCHEN CLOSET DOOR WAS RUBING DUE TO STRIKE PLATE BEING TOO FAR OUT. REMOVED SCREWS AND READJUSTED STRIKE PLATE

CORRECTION: KITCHEN CLOSET DOOR WAS RUBING DUE TO STRIKE PLATE BEING TOO FAR OUT. REMOVED SCREWS AND READJUSTED STRIKE PLATE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

Subtotal for Job #2: 32.00

Parts Total: 0.00

Labour Total: 64.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 64.00

Customer #:
1000

