

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69929
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 10765 - 2022 FREEDOM EXPRESS 287BHDS 5ZT2FEUB8NW023545
VIN: 5ZT2FEUB8NW023545 HIN: SER#: 5ZT2FEUB8NW023545
Mileage: 0 Work Order Comp: 27 FEB 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 24 FEB 23 Inv #: 387868

WO # Job # Description JOB INFORMATION

69929 3 SLIDING BR DOOR IS HARD
TRIED TO SLIDE BEDROOM DOOR BUT DOOR WOULD NOT SLIDE. REMOVED THE TRIM COVER ABOVE THE SLIDING DOOR. THEN ADJUSTED THE DOOR AT THE TOP WHERE THE ROLLER WHEELS ARE, TO PULL DOOR UP. NOTICED THE GLIDE TRACK AT THE FLOOR WAS BROKEN FROM TOO MUCH STRESS AGAINST IT FROM THE DOOR. REPLACE THE GLIDE TRACK WITH NEW. NOW THE SLIDE DOOR MOVES WITH EASE.

69929 1 BATHDOOR RUBS
TOOK PICTURES OF DOOR RUBING DOOR FRAME. OPENED THE DOOR THEN REMOVED THE LATCH PLATE, PLASTIC DOOR MOLDING. REMOVED THE STAPLES THAT HOLD THE PANEL TO THE STUD. HAMMERED THE STUD BACK AND STAPLED PANEL TO STUD. REPLACED THE PLASTIC DOOR MOLDING ONTO THE DOOR FRAME AND STAPLED IN PLACE. SCREWED THE LATCH PLATE BACK ON AND CHECKED FOR CLEARANCE. DOOR SHUTS WITH EASE.

69929 2 ENTERTAINMENT AREA ON THE BOTTOM THE WOOD IS DAMAGED
TOOK PICTURE OF DAMAGED AREA UNDER THE ENTERTAINMENT CENTER. USED A BLACK PAINT MARKER TO TOUCHUP SPOT. BLENDED THE PAINT INTO PANEL

69929 4 LIVING ROOM CLOSET DOOR RUBS
NOTICED DOOR RUBS AT THE TOP OF DOOR AND DOOR MOLDING. OPENED THE DOOR, THEN CHECKED FOR WHERE IT WAS RUBING AT. PULLED THE DOOR MOLDING OFF AT THE TOP AND PULLED THE STAPLES OUT. THE TRIM AT THE TOP TO THE LEFT WAS TOO LONG CAUSING IT TO PUSH THE

Claim : 69929

 WO # Job # Description JOB INFORMATION

DOOR MOLDING AGAINST THE DOOR. CUT THE TRIM SHORTER SO DOOR
 MOLDING SET FLUSH AGAINST THE STUD. STAPLED THE DOOR MOLDING BACK
 TO STUD. DOOR NOW SHUTS WITH EASE.

69929 5 CLIP BROKEN ON BEDROOM SLIDING DOOR LOCK.

THE METAL BUTTON THAT IS ATTACHED TO THE STRAP TO HOLD DOOR IN
 PLACE CAME APART. TOOK PICTURES OF BUTTON, REMOVED OLD BUTTON THEN
 CRIMPED IN NEW BUTTON SO THAT THE DOOR STAYS SHUT WHEN TRAVELING.

69929 6 LINO IN THE SLIDE ROOM IS A TRIP HAZZARD

TOOK PICTURE IF THE FLOOR. PICKED LINO UP THEN CUT OFF EXTRA THAT
 WAS CAUSING IT TO STICK UP. THEN LAYED BOARDS ON THE EDGE , THEN
 USED A HEAT GUN TO HELP THE FLOORING TO RELAX TO PREVENT A TRIP
 HAZARD.

Part No	Job#	Description	PARTS	Qty	Price	Total
RVDH528	3	H528 1-SET SLIDING DOOR GUIDE		1.00	4.50	4.50

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.15	160.00	24.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.15	160.00	24.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.40	160.00	64.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.40	160.00	64.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.10	160.00	16.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.50	160.00	80.00

Parts Total: 4.50
 Labour Total: 304.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 308.50

Customer Signature: _____

Date: _____