



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 69950  
Promised Date:  
21 MAR 23

## CUSTOMER WORK ORDER

WO #: 69950

Customer: 53409 - EBLEN, BARRY L. -  
270-860-4442

Tag:

Author: PH

Location: 0325 CHECK STATUS WITH  
FOREST RIVER

Stock #: 11085

Stock Desc: 2022 5W FOREST RIVER

SABRE 37FLL

Chassis #: 5ZT3SR2B3N6110862

Serial #: 5ZT3SR2B3N6110862

Mileage:

Licence:

Invoice #:

Date In: 27 FEB 23

Promised: 31 MAR 23

Date Sched:

Completed: 23 MAR 23

Warr. Date: 25 FEB 23

### Job #FPDINFW - Internal

COMPLAINT: Transferred to BAS\*70011 on 04 MAR 23

Estimate amount was 0.00

FINAL PDI ON NEW FIFTH WHEELS

CAUSE: final

CORRECTION: checked all appliances,lights,drawers,doors,electrical,plumbing,holding tanks,torqued  
lugs,checked tire pressure,installed battery and battery cables,ran lp drop test.

#### Labor

| Code   | Description                         | Mechanic | Total |
|--------|-------------------------------------|----------|-------|
| PDINFW | FINAL PDI NEW FIFTH WHEEL (INTERNAL | ZMS      | N/C   |
| PDINFW | FINAL PDI NEW FIFTH WHEEL (INTERNAL | ZMS      | N/C   |

Subtotal for Job #FPDINFW: 0.00

### Job #WALK - Internal

Transferred to BAS\*70011 on 04 MAR 23

Estimate amount was 180.00

WALK THRU

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) |          | N/C   |

Subtotal for Job #WALK: 0.00

### Job #WINTER - Internal

COMPLAINT: Transferred to BAS\*70011 on 04 MAR 23

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*

NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: winterize

CORRECTION: ran a.f. through all lines and fixtures

#### Labor

| Code | Description    | Mechanic | Total |
|------|----------------|----------|-------|
| Z990 | WINTERIZE UNIT | ZMS      | N/C   |



Customer #:  
53409



## Other Services

| Code | Description   | Qty  | Price | Total |
|------|---------------|------|-------|-------|
| SS   | SHOP SUPPLIES | 0.00 | N/C   | N/C   |

**Subtotal for Job #WINTER: 0.00**

### Job #1 - Internal

COMPLAINT: Transferred to BAS\*70011 on 04 MAR 23

Estimate amount was 0.00

INSTALL TANKLESS WATER HEATER

CAUSE: remove original water heater and install tankless water heater.

CORRECTION: removed outdoor flange, gas line, unhooked water lines, cut wires to water heater. pulled water heater out. had to build a frame to secure new water heater and door hardware. installed framing and secured with screws. placed underbelly tape over frame. secured water heater to frame. installed door flange with putty tape on back. secured to wall and water heater flange. sealed with silicone. removed inside controll panel to gain access to original water heater switch and to mount new controll panel for water heater. cut out hole for wires on panel. took fish tape and ran communication wires through the wall and floor down to the water heater. secured wires to water heater. secured gas line. re ran hot and cold water lines to fit the new water heater. secured water lines. hooked up water to test for leaks and function. ran hot water through all lines. cleaned up area.

### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |

**Subtotal for Job #1: 0.00**

### Job #2 - Internal

COMPLAINT: Transferred to BAS\*70011 on 04 MAR 23

Estimate amount was 0.00

SWAP TRADE BR TV TO NEW UNIT BR

CORRECTION: removed tv from old camper the mounted into new camper in master bedroom. checked signal on both tvs.

### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | SAR      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | GAH      | N/C   |

**Subtotal for Job #2: 0.00**

### Job #3 - Warranty

COMPLAINT: CIELING PANEL SAGGING IN REAR TOP BUNK AREA

CAUSE: ceiling panel and trim is hanging down.

CORRECTION: removed plastic trim and pulled down ceiling panel. moved track that holds trim over so it is centered. secured ceiling panels with staples. trim plastic trim so it wouldnt push downward. ceiling panel cracked when i was removing it. added 2 pieces of trim to cover. cleaned up mess.

### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 0.00  |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 48.00 |

**Subtotal for Job #3: 48.00**





#### Job #4 - Warranty

COMPLAINT: LOWER BODY MODING ON LEFT REAR BOWING OUT

CAUSE: secure trim that has come loose.

CORRECTION: secured with screws and sealed with silicone.

| Labor                |                             |          |       |
|----------------------|-----------------------------|----------|-------|
| Code                 | Description                 | Mechanic | Total |
| Z990                 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 0.00  |
| Z990                 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 32.00 |
| Subtotal for Job #4: |                             |          | 32.00 |

#### Job #5 - Warranty

COMPLAINT: BULB SEAL NEEDS REPLACED ON TWO SEPERATE SLIDE OUTS

CAUSE: bul seal is damaged on front living room slkide out and rear wardrobe slide out.

CORRECTION: replaced 2 sections of bulb seal. TOOK PICS FOR WARRANTY  
 helped other tech with picture and measuring seals

| Labor |                             |          |        |
|-------|-----------------------------|----------|--------|
| Code  | Description                 | Mechanic | Total  |
| Z990  | MISC LABOUR CODE (EXTERNAL) | ZMS      | 105.60 |
| Z990  | MISC LABOUR CODE (EXTERNAL) | ZMS      | 172.80 |
| Z990  | MISC LABOUR CODE (EXTERNAL) | SAR      | 121.60 |

| Parts                |                                                                                                       |       |       |        |
|----------------------|-------------------------------------------------------------------------------------------------------|-------|-------|--------|
| Part #               | Description                                                                                           | Qty   | Price | Total  |
| 20X48346A            | SLIDE OUT, BULB "D" SEAL 1.20" X<br>LENGTH SLIP<br>ONTOP/SIDES/BOTTOM-ABOVE -<br>BLACK LARGE "D" SEAL | 10.00 | 0.87  | 8.70   |
| Subtotal for Job #5: |                                                                                                       |       |       | 408.70 |

#### Job #6 - Internal

Transferred to BAS\*70011 on 04 MAR 23

Estimate amount was 0.00

SWAP ANDERSEN HITCH FROM TRADE

| Labor                |                             |          |       |
|----------------------|-----------------------------|----------|-------|
| Code                 | Description                 | Mechanic | Total |
| Z990                 | MISC LABOUR CODE (EXTERNAL) | GAH      | N/C   |
| Subtotal for Job #6: |                             |          | 0.00  |

Parts Total: 8.70  
 Labour Total: 480.00  
 Sublet Total: 0.00  
 Extras Total: 0.00  
**WORK ORDER TOTAL: 488.70**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer Signature : \_\_\_\_\_

Date: 23 Mar 2023

W/O: 69950  
Promised Date:  
31 MAR 23



Customer #:  
53409

