



Warranty Authorization Form

Date: 3/6/2023

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725

Ph. (812) 867-5200

General Information

Pre-Auth #: 33564

Unit: 7M5FV392XNA006211

Series: Valor

Model: 2022VAL36V11

Notes: 3/1 DH: These will need to be put on 2 different job lines. As 1 need repaired / Action. The other one doesn't need repaired / in-action.

Status: Approved

Dealer Information

American RV
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725

Requestor: Ben Hoffman

Return Fax #:

Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 22563 22V512 - Lippert Awning Recall (LCI # 22E-055). .30hrs *Fault Code:* RECALL-INACTION
for Inspection Only. .30hrs for Repair. 1.50hrs for Replacement

Serial #: RPO-0007577866

Model #: V000332996

Notes:

Problem: #22-434 LIPPERT AWNING RECALL (INSPECTION)THIS IS FOR THE FRONT
AWNING

Time Requested: .3

Cause: #22-434 LIPPERT AWNING RECALL (INSPECTION)

Time Allowed: .3

Remedy: CAMPER HAS TWO LIPPERT AWNINGS.TOOK PICTURES TO SHOW BOTH
AWNINGS. TOOK PICTURES OF FACTORY TAGS ON AWNINGS. THE BACK AWNING IS IN
GOOD SHAPE NO TEARS,CUTS, OR RIPS. THE FRONT AWNING IS SHOWING THE AWNING
FABRIC PEELING ON THE REAR OF CANVAS AT THE TOP. PUT BLUE TAPE ON THE FRONT
AWNING AT THE TAG AND DAMAGED AREA TO IDENTIFY IT AND SHOWING THE DAMAGE.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved

Operation Line 2

Flat Rate Code: 22563 22V512 - Lippert Awning Recall (LCI # 22E-055). .30hrs *Fault Code:* RECALL-ACTION
for Inspection Only. .30hrs for Repair. 1.50hrs for Replacement

Serial #: RPO-0008013320

Model #: V000515432

Notes:

Problem: #22-434 LIPPERT AWNING RECALL (INSPECTION) THIS IS FOR THE REAR
AWNING

Time Requested: .6

Time Allowed: .6

Cause: #22-434 LIPPERT AWNING RECALL (INSPECTION)

Sublet Repairs: 0.00

Remedy: CAMPER HAS TWO LIPPERT AWNINGS. TOOK PICTURES TO SHOW BOTH
AWNINGS. TOOK PICTURES OF FACTORY TAGS ON AWNINGS. THE BACK AWNING IS IN
GOOD SHAPE NO TEARS, CUTS, OR RIPS. THE FRONT AWNING IS SHOWING THE AWNING
FABRIC PEELING ON THE REAR OF CANVAS AT THE TOP. PUT BLUE TAPE ON THE FRONT
AWNING AT THE TAG AND DAMAGED AREA TO IDENTIFY IT AND SHOWING THE DAMAGE.

Part Return Req: No

Status: Approved