

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69966
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11257 - 2023 SPRINGDALE 1800BH 4YDTSGG18PW102360
VIN: 4YDTSGG18PW102360 HIN: SER#: 4YDTSGG18PW102360
Mileage: 0 Work Order Comp: 13 MAR 23
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 28 FEB 23 Inv #: 388456

WO # Job # Description JOB INFORMATION

69966 2 BATHROOM DOOR HITTING STRIKER PLATE CAUSING IT NOT TO CLOSE
BATHROOM DOOR WAS HITTING STRIKE PLATE CAUSING DOOR NOT TO CLOSE.
STRIKE PLATE NEEDED ADJUSTED. ADJUSTED STRIKEPLATE TO ALLOW DOOR
TO CLOSE PROPERLY
BATHROOM DOOR WAS HITTING STRIKE PLATE CAUSING DOOR NOT TO CLOSE.
STRIKE PLATE NEEDED ADJUSTED. ADJUSTED STRIKEPLATE TO ALLOW DOOR
TO CLOSE PROPERLY
69966 3 KITCHEN DRAWER HARD TO CLOSE / CATCHING
kitchen top drawer was hard to latch and wouldnt carch due to a
screw sticking part way out in rail causing it hit and not close.
removed and switched with a smaller screw and then tested drawer
kitchen top drawer was hard to latch and wouldnt carch due to a
screw sticking part way out in rail causing it hit and not close.
removed and switched with a smaller screw and then tested drawer
69966 4 SHOWER SURROUND NEEDS SEALED
shower surround not sealed up needed sealed
shower surround not sealed up needed sealed
69966 5 BUNK SUPPORT IS LOOSE
bunk bed suppons were not stapled in and wer laying on fresh
tank. reinstalled supports and added screws for extra support No
damage was done to fresh tank
bunk bed suppons were not stapled in and wer laying on fresh
tank. reinstalled supports and added screws for extra support No

Claim : 69966

 WO # Job # Description JOB INFORMATION

damage was done to fresh tank

69966 6 KITCHEN SINK DRAIN PIPE MISSING CONE WASHER
 KITCHEN SINK DRAIN PIPE MISSING CONE WASHER. WHEN I RUN WATER AND
 IT STARTED LEAKING DUE TO FACTORY NOT INSTALLING CONE WASHER.
 INSTALLED NEW CONE WASHER AND TESTED FOR LEAKS. NO LEAKS AFTER
 INSTALLATION OF CONE WASHER
 KITCHEN SINK DRAIN PIPE MISSING CONE WASHER. WHEN I RUN WATER AND
 IT STARTED LEAKING DUE TO FACTORY NOT INSTALLING CONE WASHER.
 INSTALLED NEW CONE WASHER AND TESTED FOR LEAKS. NO LEAKS AFTER
 INSTALLATION OF CONE WASHER

69966 7 MAIN ENTRY DOOR NOT LATCHING PROPERLY
 MAIN ENTRY DOOR NOT LATCHING PROPERLY ITS HITTING THE STRIKE
 PLATE. STRIKE PLATE NEEDS TO BE MOVED UP. MOVED UP STRIKE PLATE
 TO GET IT TO CLOSE PROPERLEY
 MAIN ENTRY DOOR NOT LATCHING PROPERLY ITS HITTING THE STRIKE
 PLATE. STRIKE PLATE NEEDS TO BE MOVED UP. MOVED UP STRIKE PLATE
 TO GET IT TO CLOSE PROPERLEY

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	2	MISCELLANEOUS REPAIR		0.10	160.00	16.00
Z990	3	MISCELLANEOUS REPAIR		0.10	160.00	16.00
Z990	4	MISCELLANEOUS REPAIR		0.50	160.00	80.00
Z990	5	MISCELLANEOUS REPAIR		0.20	160.00	32.00
Z990	6	MISCELLANEOUS REPAIR		0.30	160.00	48.00
Z990	7	MISCELLANEOUS REPAIR		0.20	160.00	32.00

Parts Total: 0.00
 Labour Total: 224.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>>> Claim Total: 224.00

Customer Signature: _____

Date: _____