



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69966
Promised Date:
28 FEB 23

CUSTOMER WORK ORDER

WO #: 69966

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: PH

Location: 0313 BH TO CLOSE
WARRANTY

Stock #: 11257

Stock Desc: 2023 TT KEYSTONE

SPRINGDALE 1800BH

Chassis #: 4YDTSGG18PW102360

Serial #: 4YDTSGG18PW102360

Mileage: 0

Licence:

Invoice #:

Date In: 28 FEB 23

Promised: 28 FEB 23

Date Sched:

Completed: 13 MAR 23

Warr. Date:

Job #SUMMERLAND - Internal

COMPLAINT: SUMMERLAND PDI

CAUSE: PDI NEW TRAVEL TRAILER

CORRECTION: PDI NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	2.00	N/C	N/C
11-1161	1-1/2" TRAP ADAPTER-FPT	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	0.00	N/C	N/C
FRT	UPS-FITTING	1.00	N/C	N/C

Subtotal for Job #SUMMERLAND: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: WINTERIZED NEW UNIT TOOK 1 GAL

CORRECTION: WINTERIZED NEW UNIT TOOK 1 GAL

Labor



Customer #:
1000

W/O: 69966
Promised Date:
28 FEB 23



Customer #:
1000



Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	RAB	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: BUNK LIGHT LENDS MISSING

CAUSE: TOP BUNK LIGHT LENS IS MISSING NEEDS NEW ONE

CORRECTION: TOP BUNK LIGHT LENS IS MISSING NEEDS NEW ONE

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	RAB	0.00

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: BATHROOM DOOR HITTING STRIKER PLATE CAUSING IT NOT TO CLOSE

CAUSE: BATHROOM DOOR WAS HITTING STRIKE PLATE CAUSING DOOR NOT TO CLOSE. STRIKE PLATE NEEDED ADJUSTED. ADJUSTED STRIKEPLATE TO ALLOW DOOR TO CLOSE PROPERLY

CORRECTION: BATHROOM DOOR WAS HITTING STRIKE PLATE CAUSING DOOR NOT TO CLOSE. STRIKE PLATE NEEDED ADJUSTED. ADJUSTED STRIKEPLATE TO ALLOW DOOR TO CLOSE PROPERLY

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	16.00

Subtotal for Job #2: 16.00

Job #3 - Warranty

COMPLAINT: KITCHEN DRAWER HARD TO CLOSE / CATCHING

CAUSE: kitchen top drawer was hard to latch and wouldnt carch due to a screw sticking part way out in rail causing it hit and not close. removed and switched with a smaller screw and then tested drawer

CORRECTION: kitchen top drawer was hard to latch and wouldnt carch due to a screw sticking part way out in rail causing it hit and not close. removed and switched with a smaller screw and then tested drawer

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	16.00

Subtotal for Job #3: 16.00

Job #4 - Warranty

COMPLAINT: SHOWER SURROUND NEEDS SEALED

CAUSE: shower surround not sealed up needed sealed

CORRECTION: shower surround not sealed up needed sealed





Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	80.00
Subtotal for Job #4:			80.00

Job #5 - Warranty

COMPLAINT: BUNK SUPPORT IS LOOSE

CAUSE: bunk bed supports were not stapled in and were laying on fresh tank. reinstalled supports and added screws for extra support No damage was done to fresh tank

CORRECTION: bunk bed supports were not stapled in and were laying on fresh tank. reinstalled supports and added screws for extra support No damage was done to fresh tank

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	32.00
Subtotal for Job #5:			32.00

Job #6 - Warranty

COMPLAINT: KITCHEN SINK DRAIN PIPE MISSING CONE WASHER

CAUSE: KITCHEN SINK DRAIN PIPE MISSING CONE WASHER. WHEN I RUN WATER AND IT STARTED LEAKING DUE TO FACTORY NOT INSTALLING CONE WASHER. INSTALLED NEW CONE WASHER AND TESTED FOR LEAKS. NO LEAKS AFTER INSTALLATION OF CONE WASHER

CORRECTION: KITCHEN SINK DRAIN PIPE MISSING CONE WASHER. WHEN I RUN WATER AND IT STARTED LEAKING DUE TO FACTORY NOT INSTALLING CONE WASHER. INSTALLED NEW CONE WASHER AND TESTED FOR LEAKS. NO LEAKS AFTER INSTALLATION OF CONE WASHER

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	48.00
Subtotal for Job #6:			48.00

Job #7 - Warranty

COMPLAINT: MAIN ENTRY DOOR NOT LATCHING PROPERLY

CAUSE: MAIN ENTRY DOOR NOT LATCHING PROPERLY ITS HITTING THE STRIKE PLATE. STRIKE PLATE NEEDS TO BE MOVED UP. MOVED UP STRIKE PLATE TO GET IT TO CLOSE PROPERLEY

CORRECTION: MAIN ENTRY DOOR NOT LATCHING PROPERLY ITS HITTING THE STRIKE PLATE. STRIKE PLATE NEEDS TO BE MOVED UP. MOVED UP STRIKE PLATE TO GET IT TO CLOSE PROPERLEY

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	32.00
Subtotal for Job #7:			32.00

Parts Total:	0.00
Labour Total:	224.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	224.00

