



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69991
Promised Date: 24 MAR 23



Customer #:
53184



CUSTOMER WORK ORDER

WO #: 69991 (Appointment Date: 02 MAR 2023 - Time: 04:30pm)

Customer: 53184 - DIEDRICH, DOUG -
812-305-6870

Tag:

Author: BJW

Location: 0317 CHECK PREAUTH

Stock #:

Stock Desc: 2022 TT FOREST RIVER

NO BOUNDRIES 20.4

Chassis #:

Serial #: 4X4TRPV28NR207772

Mileage:

Licence:

Invoice #: 388533

Date In: 02 MAR 23

Promised: 31 MAR 23

Date Sched:

Completed: 16 MAR 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: CUSTOMER NOTICED A LITTLE BIT OF WATER NEAR THE POCKET DOOR GOING INTO THE RESTROOM. THIS IS ALSO NEAR THE SLIDROOM. CUSTOMER HAS CONTINUED TO NOTICE WATER IN THIS AREA EACH TIME THAT IT RAINS. THERE IS CURRENTLY A PAPER TOWEL IN THE FLOOR IN THE EXACT SPOT WHERE THE WATER COMES THROUGH. THIS IS TO THE LEFT OF THE SLIDEROOM.

CAUSE: pulled unit into shop. looked over roof. looked around slide room and surrounding areas for any water lines. talked to BJ about complaint. customer states water is getting into the unit while slide room is closed. pulled unit outside and hooked up sprinkler over slide room.

CORRECTION: Water is coming in on the bottom of the schwintech hardware on the front and the rear of the slide. Went outside and inspected all seals. Bulb seals are compressed on the sides and the top. Wiper seal is damaged on the rear of the slide room. Also noticed that the schwintech hardware isnt sealed in a few spots. Didn't see any major areas that are causing the leak. Remove the damaged seals from the slide room. Took old wiper seal and traced out the cutouts for the Hardware. Installed wiper seal. Installed bulb seals on both sides and top. Sealed bulb seals with silicone as needed. Secured bulb seals with screws. Letting silicone dry. Will water test afterwards to make sure slide room isn't leaking anymore.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	80.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	16.84	16.84
13-1095A	SLIDE ON "D" SEAL X FT.	20.00	2.22	44.40

Subtotal for Job #1: 301.24

Job #SUMMER - External

COMPLAINT: DE-WINTERIZE UNIT

CAUSE: dewinterize

CORRECTION: ran water through all lines and fixtures. unbypassed water heater and filled.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #SUMMER:

0.00

Parts Total:

61.24

Labour Total:

240.00

Sublet Total:

0.00

Extras Total:

0.00

WORK ORDER TOTAL:

301.24

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Mar 2023

W/O: 69991
 Promised Date:
 31 MAR 23



Customer #:
 53184

