

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 1454818 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CAEC3PK005473 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 203 / 203 ITEM # BCAT164BH DEALER RO # 69997 CLAIM START DATE 03/10/2023 CLAIM END DATE 01/01/1900
Labor rate: \$160.00 OWNER INFORMATION	

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor				
Line# 1	Operation Code	Operational Description		
	02-30-101-001076	Hinged Passage Door - Adjust/Interior/Interior Doors		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-03-10 16:07:43 :: BATHROOM DOOR RUBBING bathroom door rubbing against striking plate. strikeing plate was not screwed in all they way. screwed in striking plate and it fixed the pronlem bathroom door rubbing against striking plate. strikeing plate was not screwed in all they way. screwed in striking plate and it fixed the pronlem			
	Model #	Dlr Sub Hrs	Sub Labor Amt	\$48.00
	Serial #	Appr Hrs	Appr Labor Amt	\$32.00
	Notes			
	EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO TYPICAL REPAIR TIME TO SCREW IN STRIKING PLATE			
Labor				
Line# 2	Operation Code	Operational Description		
	43-548-11-24-001297	Interior 12 Volt Wiring - Bus Electrical/Wiring - 12 Volt/Electrical/Repair		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-03-10 16:08:50 :: REFRIDGERATOR SWITCH COMING OUT OF WALL refridgerator switch had come lose. needed clipped back in refridgerator switch had come lose. needed clipped back in			
	Model #	Dlr Sub Hrs	Sub Labor Amt	\$16.00
	Serial #	Appr Hrs	Appr Labor Amt	\$16.00
	Notes			
	AUTHORIZED AS REQUESTED			
Labor				
Line# 3	Operation Code	Operational Description		
	19-60-141-001617	Shower Stall - Reseal/Plumbing/Shower, Tub Surround		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-03-10 16:10:50 :: SHOWER SURROUND NOT SEALED shower surround was not sealed up properly. removed old sealnt and added new shower surround was not sealed up properly. removed old sealnt and added new			
	Model #	Dlr Sub Hrs	Sub Labor Amt	\$16.00
	Serial #	Appr Hrs	Appr Labor Amt	\$16.00
	Notes			
	AUTHORIZED AS REQUESTED			
Labor				
Line# 4	Operation Code	Operational Description		
	01-30-102-002279	Wall Panel - Replace/Interior/Panels, Ceilings, & Interior Moldings		
	Complaint, Cause, Correction			

Original Note : bhoffman@americanrvcenter.com, 2023-03-10 16:11:39 :: STAPLES STICKING OUT ABOVE BEDROOM staples sticking out above bedroom. removed and filled holes with wood putty that matched color staples sticking out above bedroom. removed and filled holes with wood putty that matched color

Model #	Dir Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes
AUTHORIZED AS REQUESTED

Submitted	Labor Amt	\$112.00	Approved	Labor Amt	\$96.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$112.00		Total	\$96.00

DEALER _____ **DATE** _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE

All repairs described have been inspected and are satisfactory.