

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 1454842 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CAEC9PK005476 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 203 / 203 ITEM # BCAT164BH DEALER RO # CLAIM START DATE 03/10/2023 CLAIM END DATE 01/01/1900
---	---

Labor rate: \$160.00

OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code	Operational Description		
20-69-19-00-000706	Compartment Door - Exterior/Compartment Doors/Reseal/No Tread Code		

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2023-03-10 16:23:06 :: DOORSIDE COMPARTMENT NEEDS SEALED DOORSIDE COMPARTMENT WASNT SEALED UP PROPERLY LEAVING A GAP UP TOP FOR WATER TO GET IN. REMOVED THEIR SLOPPY SEALING JOB CLEANED AND RESEALED DOORSIDE COMPARTMENT WASNT SEALED UP PROPERLY LEAVING A GAP UP TOP FOR WATER TO GET IN. REMOVED THEIR SLOPPY SEALING JOB CLEANED AND RESEALED

Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$48.00
Serial #	Appr Hrs	0.30	Appr Labor Amt	\$48.00

Notes

Labor

Line# 2

Operation Code	Operational Description		
43-548-11-24-001297	Interior 12 Volt Wiring - Bus Electrical/Wiring - 12 Volt/Electrical/Repair		

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2023-03-10 16:24:31 :: FRIDGE SWITCH IS LOOSE FRIDGE SWITCH IS LOSE. WHEN I WENT TO FIX I FOUND THE WIRES WERE BARLEY CONNECTED. REINSTALLED WIRES AND ATTACHED FRIDGE ON AND OFF SWITCH CORRECTLEY

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.10	Appr Labor Amt	\$16.00

Notes

EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO TYPICAL REPAIR TIME TO SECURE SWITCH

Labor

Line# 3

Operation Code	Operational Description		
02-30-101-001076	Hinged Passage Door - Adjust/Interior/Interior Doors		

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2023-03-10 16:25:32 :: BATHROOM DOOR RUBBING CAUSING DOOR NOT TO SHUT RIGHT BATHROOM DOOR RUBBING AGAINST STRIKE PLATE CAUSING DOOR NOT TO SHUT. ADJUSTED STRIKE PLATE TO ALLOW DOOR TO SHUT RIGHT BATHROOM DOOR RUBBING AGAINST STRIKE PLATE CAUSING DOOR NOT TO SHUT. ADJUSTED STRIKE PLATE TO ALLOW DOOR TO SHUT RIGHT

Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$48.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes

EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO TYPICAL REPAIR TIME TO SECURE STRIKE PLATE

Labor
Line# 4

Operation Code
01-30-102-001117

Operational Description
Trim Molding, each - Replace/Interior/Panels, Ceilings, & Interior Moldings

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-03-10 16:26:49 :: BATTON STRIP IN BEDROOM HANGING DOWN BATTON STRIP IN BEDROOM WAS HANGING DOWN MISSING STAPLES. RESTAPLED AND FILLED IN HOLES BATTON STRIP IN BEDROOM WAS HANGING DOWN MISSING STAPLES. RESTAPLED AND FILLED IN HOLES

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes
AUTHORIZED AS REQUESTED

Submitted

Labor Amt	\$160.00
Parts & Freight	\$0.00
Total	\$160.00

Approved

Labor Amt	\$128.00
Parts & Freight	\$0.00
Total	\$128.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.