

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1452677
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAEC7PK005475
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT164BH
		DEALER RO #	69999
		CLAIM START DATE	03/09/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code	Operational Description		
01-70-506-001800	Refrigerator Door - Replace/Appliances/Refrigerator		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2023-03-09 12:12:38 :: FRIDGE DOOR TRAY HOLDER CLIP BROKE FRIDGE DOOR WHRE THE CAN HOLDER GOES THE CLIP IS BROKE/CRACKED ON THE FRIDGE ITSELF NEEDS NEW ONE FRIDGE DOOR WHRE THE CAN HOLDER GOES THE CLIP IS BROKE/CRACKED ON THE FRIDGE ITSELF NEEDS NEW ONE			
Model #	GPV10FSNBSB	Dlr Sub Hrs	1.00
Serial #	HT589817	Appr Hrs	0.20
		Sub Labor Amt	\$160.00
		Appr Labor Amt	\$32.00

Notes

EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO TYPICAL REPAIR TIME FOR REFRIGERATOR DOOR CLIP

Labor

Line# 2

Operation Code	Operational Description		
30-92-01-00-001163	Ceiling Fan Light Globe - Interior/Interior Miscellaneous/Replace/No Tread Code		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2023-03-09 12:14:21 :: LIGHT LENS MISSING ABOVE BUNK LIGHT LENS ABOVE BUNK MISSING. NEED NEW ONE LIGHT LENS ABOVE BUNK MISSING. NEED NEW ONE			
Model #		Dlr Sub Hrs	0.10
Serial #		Appr Hrs	0.10
		Sub Labor Amt	\$16.00
		Appr Labor Amt	\$16.00

Notes

Labor

Line# 3

Operation Code	Operational Description		
19-60-141-001617	Shower Stall - Reseal/Plumbing/Shower, Tub Surround		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2023-03-09 12:15:03 :: SHOWER SURROUND NEEDS SEALED SHOWER SURROUND WAS NOT SEALED PROPERLEY. SCRAPED OFF OLD SEALANT AND SEALED UP SHOWER SURROUND WAS NOT SEALED PROPERLEY. SCRAPED OFF OLD SEALANT AND SEALED UP			
Model #		Dlr Sub Hrs	0.20
Serial #		Appr Hrs	0.20
		Sub Labor Amt	\$32.00
		Appr Labor Amt	\$32.00

Notes

AUTHORIZED AS REQUESTED

Labor

Line# 4

Operation Code	Operational Description
01-60-139-001563	Kitchen Sink - Replace/Plumbing/Kitchen (Galley) Sink

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-03-09 12:15:45 :: KITCHEN SINK NEEDS SEALED
KITCHEN SINK WAS NOT SEALED UP. SEALED UP KITCHEN SINK KITCHEN SINK WAS NOT SEALED UP.
SEALED UP KITCHEN SINK

Model #	Dlr Sub Hrs	0.10	Sub Labor Amt	\$16.00
Serial #	Appr Hrs	0.10	Appr Labor Amt	\$16.00

Notes

AUTHORIZED AS REQUESTED

Labor**Line# 5****Operation Code**

40-108-01-11-001330

Operational Description

Interior GFI - Electrical/110 Volt Interior/Replace/Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-03-09 12:16:39 :: GFCI OUTLET ON EXTERIOR
NEEDS SEALED GFCI OUTLET EXTERIOR WASNT SEALED . CLANED URFACED AND SEALED UP GFCI
OUTLET EXTERIOR WASNT SEALED . CLANED URFACED AND SEALED UP

Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$48.00
Serial #	Appr Hrs	0.30	Appr Labor Amt	\$48.00

Notes**Labor****Line# 6****Operation Code**

20-55-01-00-003681

Operational Description

Awning Arm, each - Exterior/Awnings - Electrical (Carefree of Colorado)/
Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-03-09 12:20:09 :: AWNING ARM SCREW BACKING
OUT AWNING ARM SCREW BACKED OUT CAUSING AWNING WHEN COMING OUT TO COLLAPSE. REMOVED
SCREW AND INSTALLED A NEW LONGER SCREW AWNING ARM SCREW BACKED OUT CAUSING AWNING
WHEN COMING OUT TO COLLAPSE. REMOVED SCREW AND INSTALLED A NEW LONGER SCREW

Model #	NA	Dlr Sub Hrs	0.50	Sub Labor Amt	\$80.00
Serial #	NA	Appr Hrs	0.50	Appr Labor Amt	\$80.00

Notes**Labor****Line# 7****Operation Code**

01-70-506-001801

Operational Description

Freezer Door - Replace/Appliances/Refrigerator

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-03-09 12:21:25 :: FREEZER DOOR HAS A DENT IN IT
FREEZER DOOR HAS DENT IN IT NEEDS NEW DOOR SEE PICS FREEZER DOOR HAS DENT IN IT NEEDS NEW
DOOR SEE PICS

Model #	GPV10FSNBSB	Dlr Sub Hrs	1.00	Sub Labor Amt	\$160.00
Serial #	HT589817	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes

EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO TYPICAL REPAIR TIME TO R/R FREEZER DOOR

Submitted

Labor Amt	\$512.00
Parts & Freight	\$0.00
Total	\$512.00

Approved

Labor Amt	\$256.00
Parts & Freight	\$0.00
Total	\$256.00

DEALER**DATE****SIGNATURE**

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER**DATE****SIGNATURE**

All repairs described have been inspected and are satisfactory.