



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70003
Promised Date: 29 APR 23

CUSTOMER WORK ORDER

WO #: 70003
Customer: 1000 - BASDEN'S
AMERICAN RV -
Tag:
Author: PH
Location: 0405 BH TO CLOSE WO

Stock #: 10874
Stock Desc: 2023 TT FOREST RIVER
CHEROKEE 306MM
Chassis #: 4X4TCKG20PX161435
Serial #: 4X4TCKG20PX161435
Mileage: 0
Licence:

Invoice #:
Date In: 03 MAR 23
Promised: 29 APR 23
Date Sched:
Completed: 31 MAR 23
Warr. Date:



Customer #:
1000



Job #PDINTT - Internal

Transferred to BAS*70218 on 30 MAR 23
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

Labor Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C
Subtotal for Job #PDINTT:				0.00

Job #1 - Warranty

COMPLAINT: STEPS HITTING FRAME

CAUSE: REAR ENTRY STEPS WERE HITTING DOOR FRAME CAUSING STEPS NOT TO GO DOWN.
NEEDS ADJUSTED

CORRECTION: REAR ENTRY STEPS WERE HITTING DOOR FRAME CAUSING STEPS NOT TO GO
DOWN. NEEDS ADJUSTED. ADJUSTED STEPS TO ALLOW THEM TO COME DOWN

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	16.00
Subtotal for Job #1:			16.00

Job #2 - Warranty

COMPLAINT: OUTSIDE KITCHEN PLATFORM FOR THE STOVE NOT ATTACHED ALL THE WAY

CAUSE: OUTSIDE KITCHEN WAS NOT ATTACHED RIGHT HAD TO ADD SCREWS AND SECURE

CORRECTION: OUTSIDE KITCHEN WAS NOT ATTACHED RIGHT HAD TO ADD SCREWS AND



SECURE

W/O: 70003
Promised Date:
29 APR 23

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	16.00
Subtotal for Job #2:			16.00

Job #3 - Warranty

COMPLAINT: REAR A/C FLUSHING E3 CODE

CAUSE: REAR AC UNIT WAS FLASHING E3 CODE . REMOVED THERMOSAT AND FOUND NOTHING WRONG . WENT TO AC PLENUM REMOVED COVER AND FOUND WIRES NOT ATTACHED FROM THE FACTORY. STRIPPED BACK WIRES AND CRIMPPED NEW CONNECTOR THEN TESTED AC UNIT.

CORRECTION: REAR AC UNIT WAS FLASHING E3 CODE . REMOVED THERMOSAT AND FOUND NOTHING WRONG . WENT TO AC PLENUM REMOVED COVER AND FOUND WIRES NOT ATTACHED FROM THE FACTORY. STRIPPED BACK WIRES AND CRIMPPED NEW CONNECTOR THEN TESTED AC UNIT.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	24.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	24.00
Subtotal for Job #3:			48.00

Job #4 - Warranty

COMPLAINT: SHOWER SURROUND NEEDS SEALED

CAUSE: SHOWER SURROUND WAS NOT SEALED UP NEEDED SEALED UP

CORRECTION: SEALED UP SHOWER SURROUND

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	48.00
Subtotal for Job #4:			48.00

Job #5 - Warranty

COMPLAINT: DRAWER IN KITCHEN RUBBING

CAUSE: DRAWER IN KITCHEN RUBBING AGAINST LOSE SCREW CAUSING DRAWER NOT TO OPEN ALL THE WAY. REEMOVED DRAWER AND TIGHTENED SCREW UP AND REINSTALLED DRAWER AND THEN TESTED DRAWER

CORRECTION: DRAWER IN KITCHEN RUBBING AGAINST LOSE SCREW CAUSING DRAWER NOT TO OPEN ALL THE WAY. REEMOVED DRAWER AND TIGHTENED SCREW UP AND REINSTALLED DRAWER AND THEN TESTED DRAWER

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00
Subtotal for Job #5:			32.00

Job #WINTER - Internal

Transferred to BAS*70218 on 30 MAR 23

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA



Customer #:
1000



****DE-WINTERIZATION IS NOT INCLUDED****
 NUMBER OF GALLONS USED _____

W/O: 70003
 Promised Date:
 29 APR 23



Labor			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	RAB	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #6 - Warranty

COMPLAINT: KITCHEN SLIDEROOM BLIND BROKEN

CAUSE: INSTALLED NEW ZEBRA BLINDS

CORRECTION: INSTALLED NEW ZEBRA BLINDS

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00

Parts				
Part #	Description	Qty	Price	Total
F100140433	SHADE, 64" X 38" ZEBRA SHADE	1.00	89.00	89.00

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-SHADE	1.00	32.07	32.07

Subtotal for Job #6: 153.07

Parts Total:	89.00
Labour Total:	192.00
Sublet Total:	0.00
Extras Total:	32.07
WORK ORDER TOTAL:	313.07

Customer #:
 1000



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 05 Apr 2023

Customer Signature : _____

