

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70017
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 10847 - 2023 CHEROKEE GREY WOLF 23MK 4X4TCKY23PK086533
VIN: 4X4TCKY23PK086533 HIN: SER#: 4X4TCKY23PK086533
Mileage: 0 Work Order Comp: 15 MAR 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 06 MAR 23 Inv #: 388512

WO # Job # Description JOB INFORMATION

70017 1 STEPS HITTING DOOR
STEPS HITTING DOOR DUE.. TO BRACKET HITTING STEP HINGES.
ADJUSTED STEP HINGES SO IT WONT HIT DOOR
STEPS HITTING DOOR DUE.. TO BRACKET HITTING STEP HINGES.
ADJUSTED STEP HINGES SO IT WONT HIT DOOR

70017 2 FRONT SIDE OF CAMPER HAS SPOTS THAT NEEDS SEALED
front side door side of camper has several spots that werent
sealed or were poorly sealed from factory. cleaned off old and
resealed with clear silicone
front side door side of camper has several spots that werent
sealed or were poorly sealed from factory. cleaned off old and
resealed with clear silicone

70017 3 GETTING E3 CODE ON THERMOSTATE
GETTING A E3 CODE ON THERMOSTATE A COMMUNICATION ERROR. I REMOVED
THERMOSTAT ALL WIRES WERE CONNECTED RIGHT. REMOVED AC LENUM AND
FOUNF THE GROUND WIRE WAS NOT ATTACHED CASUING IT TO LOSE
COMMUNICATION AND THROW THE E3 COSE. I STRPPED BACK WIRE AND
ADDED A BELLCAP AND CRIMPED. TESTED AC UNIT FOR A HR NO E3 CODE
EVER SHOWED BACK UP
GETTING A E3 CODE ON THERMOSTATE A COMMUNICATION ERROR. I REMOVED
THERMOSTAT ALL WIRES WERE CONNECTED RIGHT. REMOVED AC LENUM AND
FOUNF THE GROUND WIRE WAS NOT ATTACHED CASUING IT TO LOSE
COMMUNICATION AND THROW THE E3 COSE. I STRPPED BACK WIRE AND
ADDED A BELLCAP AND CRIMPED. TESTED AC UNIT FOR A HR NO E3 CODE

Claim : 70017

 WO # Job # Description JOB INFORMATION

EVER SHOWED BACK UP

70017 4 CABINET DRAWER IN KITCHEN STICKING
 cabniet drawer in kitchen was sticking/ it wasnt on the
 slidinding rail right. removed and reinstalled properly
 cabniet drawer in kitchen was sticking/ it wasnt on the
 slidinding rail right. removed and reinstalled properly

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.25	160.00	40.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.50	160.00	80.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.10	160.00	16.00

Parts Total: 0.00
 Labour Total: 168.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 168.00

Customer Signature: _____

Date: _____