

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1457161
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKY23PK086533
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT23MK-94
		DEALER RO #	70017
		CLAIM START DATE	03/14/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor
Line# 1

Operation Code	10-7-02-00-000141	Operational Description
Complaint, Cause, Correction	Entry Step - Frame & Chassis/Manual Entry Step/Adjust/No Tread Code	
Original Note : bhoffman@americanrvcenter.com, 2023-03-14 10:05:16 :: STEPS HITTING DOOR STEPS HITTING DOOR DUE.. TO BRACKET HITTING STEP HINGES. ADJUSTED STEP HINGES SO IT WONT HIT DOOR STEPS HITTING DOOR DUE.. TO BRACKET HITTING STEP HINGES. ADJUSTED STEP HINGES SO IT WONT HIT DOOR		
Model #	Dlr Sub Hrs	0.20
Serial #	Appr Hrs	0.20
	Sub Labor Amt	\$32.00
	Appr Labor Amt	\$32.00

Notes
Authorized as requested.

Labor
Line# 2

Operation Code	20-49-19-00-000588	Operational Description
Complaint, Cause, Correction	Front Moldings, each - Exterior/Front, Fiberglass Cap, Cab Over/Reseal/No Tread Code	
Original Note : bhoffman@americanrvcenter.com, 2023-03-14 10:05:59 :: FRONT SIDE OF CAMPER HAS SPOTS THAT NEEDS SEALED front side door side of camper has several spots that werent sealed or were poorly sealed from factory. cleaned off old and resealed with clear silicone front side door side of camper has several spots that werent sealed or were poorly sealed from factory. cleaned off old and resealed with clear silicone		
Model #	Dlr Sub Hrs	0.25
Serial #	Appr Hrs	0.25
	Sub Labor Amt	\$40.00
	Appr Labor Amt	\$40.00

Notes

Labor
Line# 3

Operation Code	40-196-24-11-001297	Operational Description
Complaint, Cause, Correction	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical	
Original Note : bhoffman@americanrvcenter.com, 2023-03-14 10:07:32 :: GETTING E3 CODE ON THERMOSTATE GETTING A E3 CODE ON THERMOSTATE A COMMUNICATION ERROR. I REMOVED THERMOSTATS ALL WIRES WERE CONNECTED RIGHT. REMOVED AC LENUM AND FOUNF THE GROUND WIRE WAS NOT ATTACHED CASUING IT TO LOSE COMMUNICATION AND THROW THE E3 COSE. I STRPPED BACK WIRE AND ADDED A BELLCAP AND CRIMPED. TESTED AC UNIT FOR A HR NO E3 CODE EVER SHOWED BACK UP GETTING A E3 CODE ON THERMOSTATE A COMMUNICATION ERROR. I REMOVED THERMOSTATS ALL WIRES WERE CONNECTED RIGHT. REMOVED AC LENUM AND FOUNF THE GROUND WIRE WAS NOT ATTACHED CASUING IT TO LOSE COMMUNICATION AND THROW THE E3 COSE. I STRPPED BACK WIRE AND ADDED A BELLCAP AND CRIMPED. TESTED AC UNIT FOR A HR NO E3 CODE EVER SHOWED BACK UP		

Model #	Dlr Sub Hrs	0.50	Sub Labor Amt	\$80.00
Serial #	Appr Hrs	0.50	Appr Labor Amt	\$80.00

Notes

Authorized as requested.

**Labor
Line# 4**

Operation Code
30-100-02-00-003062

Operational Description
Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2023-03-14 10:08:11 :: CABINET DRAWER IN KITCHEN STICKING cabniet drawer in kitchen was sticking/ it wasnt on the slidinding rail right. removed and reinstalled properly cabniet drawer in kitchen was sticking/ it wasnt on the slidinding rail right. removed and reinstalled properly

Model #	Dlr Sub Hrs	0.10	Sub Labor Amt	\$16.00
Serial #	Appr Hrs	0.10	Appr Labor Amt	\$16.00

Notes

Submitted	Labor Amt	\$168.00	Approved	Labor Amt	\$168.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$168.00		Total	\$168.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.