

**e-Authorization**

3-Authorization number PA03384506 Reference no: 70028 Status: Approved Approved by stuml Approved date 3/8/2023  
 Pricing Name Address Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTSG128N3104526 2/21/2022  
 600 E Baseline Rd  
 Evansville, IN 47725

Lu Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	4204306B Detector, LP - Rel	0.00	0.50	0.20		1	0.20	Complaint: LP DETECTOR IS GOING OFF ALL THE TIME Cause: PULLED UNIT INTO SHOP AND PLUGGED INTO SHORE POWER. L.P. DETECTOR IS BEEPING RANDOMLY. DETECTOR WILL NOT PERFORM TEST FUNCTION. IT BEEPS ONCE THEN DOES NOTHING. THERE IS NO LIGHT PRESENT ON DETECTOR AS WELL. NEED TO REPLACE. Correction: REMOVED MOUNTING SCREWS. CUT WIRES. REMOVED DAMAGED DETECTOR. INSTALLED NEW DETECTOR TO WIRES AND SECURED TO WALL. PARKED UNIT.

3-Authorization number PA03384506 0.20

For paper claims only use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the