

e-Authorization

3-Authorization number PA03393891	Reference no: 70047	Status: Approved	Approved by papca	Approved date 3/21/2023
Customer Name	Address	VIN	Retail sold on	

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFCGS22P2504330						
Item	Root of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2202124B	Grab Handle - Re	0.00	0.30	0.20		1	0.20	Complaint:HOLES ON DOOR SIDE WALL CLOSE TO ENTRY DOOR. HANDLE MISSING Cause:PART MISSING Correction:put putty on holes and found new screws and installed handle back in place and sealed. KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
2	3201808B	Decorative Wood	0.00	0.70	0.20		1	0.20	Complaint:BEDROOM DOOR WONT SHUT Cause:FOUND TRIM BROKEN AND WONT LET DOOR CLOSE Correction:trim is broke will need to order new piece. KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual Complaint:OFFICE/2ND BEDROOM DOOR WONT SHUT Cause:adjusted latch to catch. Correction:adjusted latch to catch. KRV – REPAIR ONLY approved.
3	3200214B	Door - Interior Hin	0.00	0.30	0.10		1	0.10	Complaint:REAR JACKS STROKE OUT AND THEY ARE MOUNTED TOO HIGH Cause:dropped both jacks down 1 bolt hole and reprogrammed jacks to level. Correction:dropped both jacks down 1 bolt hole and reprogrammed jacks to level. KRV – Labor time adjusted allowing for proper repair procedure to be performed.
4	1213714B	Leveling jack - Ele	0.00	0.70	0.70		1	0.50	

3-Authorization number PA03393891

1.20

r paper claims only use one pre-authorization number per warranty claim for
multiple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

e-Authorization

3/30/20
03:27:34 PM

3-Authorization number PA03393891	Reference no: 70047	Status: Approved	Approved by papca	Approved date 3/21/2023
Authorizing Name	Address	VIN	Retail sold on	

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFCGS22P2504330						
Item	Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2202124B	Grab Handle - Re	0.00	0.30	0.20		1	0.20	Complaint:HOLES ON DOOR SIDE WALL CLOSE TO ENTRY DOOR. HANDLE MISSING Cause:PART MISSING Correction:put putty on holes and found new screws and installed handle back in place and sealed. KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
2	3201808B	Decorative Wood	0.00	0.70	0.20		1	0.20	Complaint:BEDROOM DOOR WONT SHUT Cause:FOUND TRIM BROKEN AND WONT LET DOOR CLOSE Correction:trim is broke will need to order new piece. KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual
3	3200214B	Door - Interior Hin	0.00	0.30	0.10		1	0.10	Complaint:OFFICE/2ND BEDROOM DOOR WONT SHUT Cause:adjusted latch to catch. Correction:adjusted latch to catch. KRV – REPAIR ONLY approved.
4	1213714B	Leveling jack - Ele	0.00	0.70	0.70		1	0.50	Complaint:REAR JACKS STROKE OUT AND THEY ARE MOUNTED TOO HIGH Cause:dropped both jacks down 1 bolt hole and reprogrammed jacks to level. Correction:dropped both jacks down 1 bolt hole and reprogrammed jacks to level. KRV – Labor time adjusted allowing for proper repair procedure to be performed.

3-Authorization number PA03393891

1.20

paper claims ~~only~~ use one pre-authorization number per warranty claim for
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the