




600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70066
Promised Date: 16 MAR 23



CUSTOMER WORK ORDER

WO #: 70066
Customer: 53382 - MARTIN, MARK A. -
812-499-1786
Tag:
Author: BH
Location: 0327 CHECK PREAUTH

Stock #: 11073
Stock Desc: 2022 TT RIVERSIDE RV
RETRO 190BH
Chassis #: 59CCC4615NL004688
Serial #: 59CCC4615NL004688
Mileage:
Licence:

Invoice #:
Date In: 10 MAR 23
Promised: 16 MAR 23
Date Sched:
Completed: 27 MAR 23
Warr. Date: 16 MAR 23

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT - FINAL PDI ON NEW TRAVEL TRAILER.

CORRECTION: Moved unit into shop from sales lot. Removed LP tanks to remount battery box strap. Installed new battery. Shortened battery cables to fit. Secured all cables together. Checked all exterior lights and brakes. Brake-away switch cable broken. Replaced brake-away switch and cable. Did not have a cable to fit factory switch. Checked lug nuts and set tire pressure at 65 psi. Recorded all tire serial numbers. Checked roof and sealed holes around roof vents. Checked awning. Checked all interior lights. Added water to fresh water tank and flushed water lines. Water heater leaking at cold water inlet. Removed water line fitting and installed new fitting. Cleaned rust from pipe nipple. Wrapped nipple with teflon tape. Reinstalled water line on water heater. Filled water heater again and check for leak. No leak at this time. Performed LP drop test and set LP pressure at 10 in.wc. Checked converter output. Operated all appliances. Tv will not pick up channels inside shop. Moved unit outside and ran challes scan again. Still no channels. Removed TV Booster from mounting. Checked all coax cables. The cables going to Antenna and to Redio Ant were switched. Put cables on correct connections and TV Antenna picked up 15 channels inside shop. Moved unit to washbay area.

Customer #:
53382



Labor Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
96-8382	Trailer Breakaway System Switch; With 48 Inch Wire/ Cable And Nylon Pin Assembly	1.00	N/C	N/C
72-0839	Fresh Water Adapter Fitting; BestPEX; 1/2 Inch PEX x 1/2 Inch Female Pipe Thread Plastic Swivel End Nut	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C



Subtotal for Job #DELUXE: 0.00

Job #1 - Internal

MAGNETIC FLAG POLE HOLDER (ALREADY ON THE CAMPER) MAKE SURE IT IS ON/OR IN CAMPER

Parts				
Part #	Description	Qty	Price	Total
7142	SINGLE MAGNETIC FLAGPOLE HOLDER	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: WINTER - WINTERIZE UNIT AND DRAIN HOLDING TANKS.

CORRECTION: This model of water heater does not has a drain plug. Connected to air pressure and blew out water lines, faucets and water heater. Added antifreeze to all water lines ans faucets. Poured antifreeze in all drain traps. It required (4) gallons of antifreeze to get pink to come out of hot water faucets. Water heater does not have a drain. Drained all holdong tanks.

Labor			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	DKM	N/C
Z990	WINTERIZE UNIT	DKM	N/C

Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	4.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #WALK - Internal

COMPLAINT: WALK THRU

CORRECTION: SET UP CAMPER IN WALK THRU AREA.

Estimated Amount: 180.00

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #WALK: 0.00

Job #2 - Warranty

COMPLAINT: NO TV CHANNELS

CORRECTION: found coax cables were hooked up wrong.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	32.00

W/O: 70066
Promised Date:
16 MAR 23



Customer #:
53382



Subtotal for Job #2: 32.00

Job #3 - Internal
MEASURE AND ADJUST CUSTOMER HITCH

Labor		Mechanic	Total
Code	Description		N/C
Z990	MISC LABOUR CODE (EXTERNAL)		

Parts				
Part #	Description	Qty	Price	Total
CUR40067	PACKAGED HITCH BALL 7.5K 2 5/16IN X 1IN X 2 1/8IN	1.00	N/C	N/C
45050	CURT 4" DROP BALL MOUNT	1.00	N/C	N/C
J-30P	3/8" THREADED LINK	2.00	N/C	N/C
CUR25013	1/4IN DIAMETER SAFETY PIN W/ 12IN CHAIN PKG	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Parts Total:	0.00
Labour Total:	32.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	32.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Mar 2023

W/O: 70066
Promised Date:
16 MAR 23



Customer #:
53382

