

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70072
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 10744 - 2023 CATALINA SUMMIT SERIES 164RB 5ZT2CAEC5PK005555
VIN: 5ZT2CAEC5PK005555 HIN: SER#: 5ZT2CAEC5PK005555
Mileage: 0 Work Order Comp: 21 MAR 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 13 MAR 23 Inv #: 388728

WO # Job # Description JOB INFORMATION

70072 2 STICKERS ON FRONT CAP ARE DAMAGED
DANGER AND PROPANE STICKERS ON FRONT CAP WER TORE BEYOND
REGONTION. HAD TO TAKE HEAT GUN AND PLASTIC SCRAPER TO REMOVE OLD
DECALS. ONCE REMOVED USED CLENAER TO REMOVE ADHESIVE OFF OF OLD
DECAL ON THE CAP. LET IT DRY. ONCE DRYED I ADDED TWO NEW ONES ON
AND SMOOTHED OUT
DANGER AND PROPANE STICKERS ON FRONT CAP WER TORE BEYOND
REGONTION. HAD TO TAKE HEAT GUN AND PLASTIC SCRAPER TO REMOVE OLD
DECALS. ONCE REMOVED USED CLENAER TO REMOVE ADHESIVE OFF OF OLD
DECAL ON THE CAP. LET IT DRY. ONCE DRYED I ADDED TWO NEW ONES ON
AND SMOOTHED OUT
70072 1 FRONT COMPARTMENT DOOR LOCK BROKEN
FRONT COMPAARTMENT DOOR WOULDNT IOOPEN. HAD TO PRY OPEN. FOUND THE
NUT ATTACHONG LOCK ON VACK SIDE OF COMARTMENT WAS EXTREMELY TIGHT
CAUSING IT NOT TO TURN. LOSENEED NUT AND TESTED FUNCTION
FRONT COMPAARTMENT DOOR WOULDNT IOOPEN. HAD TO PRY OPEN. FOUND THE
NUT ATTACHONG LOCK ON VACK SIDE OF COMARTMENT WAS EXTREMELY TIGHT
CAUSING IT NOT TO TURN. LOSENEED NUT AND TESTED FUNCTION
70072 3 ENTRY DOOR LATCH NEEDS ADJUSTED
entry door latch needed adjusted , striking plate was to far back
causing door not latch properley. removed striking plate and
reinstalled and moved up then tested door
entry door latch needed adjusted , striking plate was to far back
causing door not latch properley. removed striking plate and

Claim : 70072

 WO # Job # Description JOB INFORMATION

reinstalled and moved up then tested door

70072 4 BRAKE AWAY CABLE GOING TO BATTERY NOT CONNECTED PROPERLY
 brake away cable going to battery was not crimped properly from
 factory, it was barely attached and was showing expose wiring
 causing brake control not work. vut off old connector stripped
 back new wire and crimped on new connection. attached to battery
 and tested brake away
 brake away cable going to battery was not crimped properly from
 factory, it was barely attached and was showing expose wiring
 causing brake control not work. vut off old connector stripped
 back new wire and crimped on new connection. attached to battery
 and tested brake away

70072 5 FRIDGE WONT TURN ON
 fridge would not turn on when you hit the switch. removed switch
 and founf one wire wasnt even connected and the other was barley
 crimped on to the wire. i also had remove fridge as the fridge
 was sitting on the wire providing no slack which caused
 connection to come lose at switch. crimped on a new connection
 and reattached the other two switch. reinstalled switch and
 fridge and tested for functionality
 fridge would not turn on when you hit the switch. removed switch
 and founf one wire wasnt even connected and the other was barley
 crimped on to the wire. i also had remove fridge as the fridge
 was sitting on the wire providing no slack which caused
 connection to come lose at switch. crimped on a new connection
 and reattached the other two switch. reinstalled switch and
 fridge and tested for functionality

Part No	Job#	Description	PARTS	Qty	Price	Total
C01299075	2	LABEL, USA MASS LABEL INFO (LARG		1.00	3.76	3.76

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.10	160.00	16.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.10	160.00	16.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.30	160.00	48.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.60	160.00	96.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	2	FREIGHT		1.00	15.84	15.84

Claim : 70072

Excode Job# Description EXTRAS Qty Price Total

Parts Total: 3.76
Labour Total: 208.00
Sublet Total: 0.00
Extras Total: 15.84
>>>> Claim Total: 227.60

Customer Signature: _____

Date: _____