

# FOREST RIVER WARRANTY CLAIM FORM

|   |  |
|---|--|
| <b>DEALER ACCOUNT #</b> 0005106<br>BASDEN RV CENTER INC<br>DBA AMERICAN RV CENTER<br>600 E BASELINE ROAD<br>EVANSVILLE, IN 47725<br>USA | <b>CLAIM STATUS</b> Authorized<br><b>CLAIM</b> 1473902<br><b>CLAIM ORIGIN</b> WEB<br><b>ORIGINAL CLAIM ID</b><br><b>VIN</b> 5ZT2CARBXP041750<br><b>CHASSIS VIN</b><br><b>MILEAGE</b> 0<br><b>SITE/WAREHOUSE</b> 103 / 103<br><b>ITEM #</b> CAT263BHSCKLE<br><b>DEALER RO #</b> 70074<br><b>CLAIM START DATE</b> 03/28/2023<br><b>CLAIM END DATE</b> 01/01/1900 |
| <b>Labor rate:</b> \$160.00<br><b>OWNER INFORMATION</b>   |  |

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**

|  |   |      |                               |
|--|---|------|-------------------------------|
| <b>Operation Code</b>  | <b>Operational Description</b>                                |      |                               |
| 20-68-24-00-000697   | Patio Screen Door - Exterior/Patio Doors/Repair/No Tread Code |      |                               |
| <b>Complaint, Cause, Correction</b>  |   |      |                               |
| Original Note : bhoffman@americanrvcenter.com, 2023-03-28 10:54:42 :: SCREEN DOOR NEEDS ADJUSTED ADJUSTED SCREEN DOOR LATCH AND HANDLE |   |      |                               |
| <b>Model #</b>   | <b>Dlr Sub Hrs</b>  | 0.20 | <b>Sub Labor Amt</b> \$32.00  |
| <b>Serial #</b>  | <b>Appr Hrs</b>   | 0.20 | <b>Appr Labor Amt</b> \$32.00 |

**Notes**  
AUTHORIZE AS REQUESTED

### Labor

**Line# 2**

|  |   |      |                               |
|--|---|------|-------------------------------|
| <b>Operation Code</b>  | <b>Operational Description</b>                |      |                               |
| 02-20-66-000664  | Entry Door - RV - Adjust/Exterior/Entry Doors |      |                               |
| <b>Complaint, Cause, Correction</b>  |   |      |                               |
| Original Note : bhoffman@americanrvcenter.com, 2023-03-28 10:55:44 :: ENTRY DOOR NEEDS ADJUSTED SPRAY LUBE IN PLUNGER ON DOOR, AND ADJUSTED STRIKE PLATE |   |      |                               |
| <b>Model #</b>   | <b>Dlr Sub Hrs</b>                            | 0.20 | <b>Sub Labor Amt</b> \$32.00  |
| <b>Serial #</b>  | <b>Appr Hrs</b>                               | 0.20 | <b>Appr Labor Amt</b> \$32.00 |

**Notes**  
AUTHORIZE AS REQUESTED

### Labor

**Line# 3**

|  |   |      |                               |
|--|---|------|-------------------------------|
| <b>Operation Code</b>  | <b>Operational Description</b>                        |      |                               |
| 12-60-138-001560   | P-Trap - Resecure or Tighten/Plumbing/Drainage System |      |                               |
| <b>Complaint, Cause, Correction</b>  |   |      |                               |
| Original Note : bhoffman@americanrvcenter.com, 2023-03-28 10:57:06 :: THE KITCHEN SINK IS LEAKING PICS ON ONE DRIVE. THE RUBBER GASKET FOR THE STRAINER BASKET WAS UNDERNEITH THE SINK INSTEAD OF ON TOP BETWEEN BASKET AND SINK |   |      |                               |
| <b>Model #</b>   | <b>Dlr Sub Hrs</b>                                    | 0.80 | <b>Sub Labor Amt</b> \$128.00 |
| <b>Serial #</b>  | <b>Appr Hrs</b>                                       | 0.60 | <b>Appr Labor Amt</b> \$96.00 |

**Notes**  
EXCESSIVE AMOUNT REQUESTED , ADJUSTED TIME TO SIMILAR REPAIR

### Submitted

|                 |                 |
|-----------------|-----------------|
| Labor Amt       | \$192.00        |
| Parts & Freight | \$0.00          |
| <b>Total</b>    | <b>\$192.00</b> |

### Approved

|                 |                 |
|-----------------|-----------------|
| Labor Amt       | \$160.00        |
| Parts & Freight | \$0.00          |
| <b>Total</b>    | <b>\$160.00</b> |

---

**DEALER**

**DATE**

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

---

**CUSTOMER**

**DATE**

**SIGNATURE**

All repairs described have been inspected and are satisfactory.