

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

CLAIM STATUS Authorized
CLAIM 1468400
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CAWB2PX028798
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 205 / 205
ITEM # ACAT313RLTSLE
DEALER RO # 70114
CLAIM START DATE 03/23/2023
CLAIM END DATE 01/01/1900

Labor rate: \$160.00

OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** 12-603-16-24-003866 **Operational Description** Roof - Cargo Frame & Chassis/Chassis Cab/Structure/Repair
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-23 08:58:22 :: THERE IS A HOLE IN THE RUBBER ROOF MEMBRAINE THAT WAS NOTED AT WRITE UP nail or staple came up put a patch over hole nail or staple came up put a patch over hole

Model #	Dlr Sub Hrs	0.40	Sub Labor Amt	\$64.00
Serial #	Appr Hrs	0.40	Appr Labor Amt	\$64.00

Notes

Labor

Line# 2 **Operation Code** 20-66-01-17-000671 **Operational Description** Lock Cylinder & Keys - Exterior/Entry Doors/Replace/Latch
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-23 08:59:25 :: THE KEYS DO NOT FIT. 364 is on the door handel and keys, remove handel and find 358 is # on lock, get ring of keys and have parts to cut 2 keys, PARTS IS OUT OF BLANKS WILL HAVE TO GET SOME IN, PARTS GAVE KEYS THAT FIT PUT ON RING AND REMOVE KEYS THAT DO NOT FIT UNIT TAKE KEYS TO SALES

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes

Labor

Line# 3 **Operation Code** 30-307-01-00-000920 **Operational Description** Fireplace Remote Control - Interior/Fireplace/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-23 09:00:42 :: THERE IS NO REMOTE FOR THE FIRE PLACE turn in po for remote PUT REMOTE IN FIRE PLACE

Model #	Dlr Sub Hrs	0.05	Sub Labor Amt	\$8.00
Serial #	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes

Part only

Labor

Line# 4 **Operation Code** 24-70-147-001769 **Operational Description** TV Coax Cable - Repair/Appliances/Television
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-23 09:01:59 :: NO TV CHANNELS pull booster

from wall and traced wires, found antenna wire not striped at booster, antenna wire not striped at antenna, out side TV coneted to sat pass through on booster, bedroom TV coneted to to cable in on booter pull booster from wall and traced wires, found antenna wire not striped at booster, antenna wire not striped at antenna, out side TV coneted to sat pass through on booster, bedroom TV coneted to to cable in on booter, rewire TVs and install spliter on TV 2 out and conet up bedroom and outside TV to spliter, connet up cable wire to cable in, put new ends on TV antenna wire and test, with a shop antenna conneted on roof in place of unit antenna getting stations now at all TV locations, unit antenna not picking up pull unit out side and test finlly getting chanel through antenna

Model #

Serial #

Dlr Sub Hrs

Appr Hrs

2.50

2.50

Sub Labor Amt

Appr Labor Amt

\$400.00

\$400.00

Notes

Submitted

Labor Amt	\$504.00
Parts & Freight	\$0.00
Total	\$504.00

Approved

Labor Amt	\$496.00
Parts & Freight	\$0.00
Total	\$496.00

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.