



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

WO: 70114
Promised Date:
24 MAR 23

CUSTOMER WORK ORDER

WO #: 70114

Customer: 1000 - BASDEN'S

AMERICAN RV -

Tag:

Author: BJW

Location: 0403 SEE IF CRAIG HAS A

INVOICE YET

Stock #: 10871

Stock Desc: 2023 TT COACHMEN

CATALINA 313RLTSLE

Chassis #: 5ZT2CAWB2PX028798

Serial #: 5ZT2CAWB2PX028798

Mileage: 0

Licence:

Invoice #:

Date In: 17 MAR 23

Promised: 31 MAR 23

Date Sched:

Completed: 31 MAR 23

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CORRECTION: PDI UNIT FOUND HOLE IN RUBBER ROOF, TV WILL NOT PICK UP STATIONS T ANY ANTENA OUT PUT, CHECK WATER SYSTEM WATER HEATER FILL TANKS, TOILET, SHOWER, OUT SIDE SHOWER, OUT SIDE SPRAY PORT, 2 SINKS, WASHER CONETONS, CHECK ELETRICK SYSTEM, FILL LP TANKS RUN LP DROP TEST, DRAIN AND BLOW OUT WATER SYSTEM, PUMP IN 3 GALLONS OF ANTIFREEZE THROUGH RESET BYPASS VALVES, CHECK 2 ACs, PEAL PLASTIC AND TAPE OFF OF REFER, MICROWAVE, RANGE, CLOSSET DOORS,

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JP	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: TRAILER HAD RIGHT FRONT TIRE BLOWOUT ON TRIP FROM ELKHART TO HERE WITH KEITH. WHEEL AND TIRE WILL NEED TO BE REPLACED ALONG WITH DAMAGE TO UNDER CARRIAGE OF TRAILER.

CORRECTION: jack up unit, remove tire run room out about 6 ins to mhave room to work, cut out torn underbelly get insolation and cut too fill in missing under floor, get J rap and cut to fit, install, tape seal around metal, put shop tire back on, close up unit and put out on sales lot and open up JARRON PUT TIRE ON CAMPER. WENT OUT TO CAMPER TO PUT THE FIREPLACE REMOTE



Customer #:
1000



INSIDE WITH THE OTHER REMOTES.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts				
Part #	Description	Qty	Price	Total
F100100853	WHEEL ASSY, SILVER ALUM ORACLE ST225/75R15 LRE 15X6 6X5.5 FSLW6RE5EN	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-WHEEL ASSEMBLY	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Warranty

COMPLAINT: THERE IS A HOLE IN THE RUBBER ROOF MEMBRAINE THAT WAS NOTED AT WRITE UP

CAUSE: nail or staple came up put a patch over hole

CORRECTION: nail or staple came up put a patch over hole

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	64.00
Subtotal for Job #2:			64.00

Job #3 - Warranty

COMPLAINT: THE KEYS DO NOT FIT.

CORRECTION: 364 is on the door handel and keys, remove handel and find 358 is # on lock, get ring of keys and have parts to cut 2 keys,

PARTS IS OUT OF BLANKS WILL HAVE TO GET SOME IN,

PARTS GAVE KEYS THAT FIT PUT ON RING AND REMOVE KEYS THAT DO NOT FIT UNIT

TAKE KEYS TO SALES

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	16.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	16.00

Parts				
Part #	Description	Qty	Price	Total
20-0798	GLOBAL KEY BLANKS	2.00	3.92	7.84
Subtotal for Job #3:				39.84

Job #4 - Warranty

COMPLAINT: THERE IS NO REMOTE FOR THE FIRE PLACE

CORRECTION: turn in po for remote

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00

Parts				
Part #	Description	Qty	Price	Total
F100307355	FIRELACE REMOTE	1.00	18.50	18.50



W/O: 70114
Promised Date:
31 MAR 23



Customer #:
1000



Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	15.82	15.82
Subtotal for Job #4:				34.32

Job #5 - Warranty

COMPLAINT: NO TV CHANNELS

CAUSE: pull booster from wall and traced wires, found antenna wire not striped at booster, antenna wire not striped at antenna, out side TV coneted to sat pass through on booster, bedroom TV coneted to to cable in on booter

CORRECTION: pull booster from wall and traced wires, found antenna wire not striped at booster, antenna wire not striped at antenna, out side TV coneted to sat pass through on booster, bedroom TV coneted to to cable in on booter, rewire TVs and install splitter on TV 2 out and conet up bedroom and outside TV to splitter, connet up cable wire to cable in, put new ends on TV antenna wire and test, with a shop antenna conneted on roof in place of unit antenna getting stations now at all TV locations, unit antenna not picking up pull unit out side and test finlly getting chanel through antenna

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	400.00

Parts

Part #	Description	Qty	Price	Total
532542	COAX SPLITTER	1.00	8.84	8.84
Subtotal for Job #5:				408.84

Job #6 - Internal

COMPLAINT: UNIT HAS TWO GREY TANKS BUT THERE IS ONLY ONLY GREY TANK ON MONITOR

CORRECTION: OPEN ACSESS PANEL AND TRACED WIRES TO BOARD FOUND, 2nd DRAIN IS FOR WASHER DRAIN NOT CONNETED TO TANKS, IN BEDROOM CLOSSET

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Subtotal for Job #6: 0.00

Parts Total: 35.18
Labour Total: 496.00
Sublet Total: 0.00
Extras Total: 15.82
WORK ORDER TOTAL: 547.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 31 Mar 2023

