

e-Authorization

3/30/20
12:09:32 PM

3-Authorization number PA03399410 Reference no: 70127 Status: Approved Approved by perrg Approved date 3/28/2023
rving Name Address VIN Retail sold on

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFM0T24N4701973	3/18/2023				
Item Root operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3201812A Decorative Wood	0.00	0.10	0.10		1	0.10	Complaint:SCRATCH ON WALL IN HALF BATH Cause:found scratch Correction:TOUCHED UP WITH PUTTY AND MARKER.
2	4205218A Microwave - Repa	0.00	0.20	0.20		1	0.20	Complaint:MICROWAVE SQUEAKS WHEN OPENING DOOR Cause:ADJUSTED MICROWAVE DOOR. Correction:ADJUSTED MICROWAVE DOOR.
3	3100816F Cabinet Door - Ad	0.00	0.20	0.10		1	0.10	Complaint:CABINET DOORS ABOVE MICROWAVE WONT SHUT COMPLETELY Cause:ADJUSTED BOTH DOORS. Correction:ADJUSTED BOTH DOORS.
4	3100816F Cabinet Door - Ad	0.00	0.20	0.20		2	0.10	Complaint:BATHROOM CABINET DOORS WONT SHUT COMPLETELY Cause:ADJUSTED DOORS. Correction:ADJUSTED DOORS.
5	3100816F Cabinet Door - Ad	0.00	0.20	0.20		1	0.10	Complaint:LATCHES IN BEDROOM ON CLOSET DOOR WONT LATCH Cause:MOVED BOTH CATCHES SO LATCHES WOULD CATCH. Correction:MOVED BOTH CATCHES SO LATCHES WOULD CATCH.
6	3100816F Cabinet Door - Ad	0.00	0.20	0.20		2	0.10	Complaint:CABINET DOORS BELOW KITCHEN SINK WILL NOT STAY SHUT Cause:ADJUSTED BOTH DOORS TO SHUT. Correction:ADJUSTED BOTH DOORS TO SHUT.
7	4117514A Furnace - Atwood	0.00	2.50	1.00		1	0.40	Complaint:FURNANCE FAN IS LOUD Cause:TOOK OUTSIDE COVER OFF,TOOK SCREWS OUT OF FURNANCE AROUND OUTSIDE PLATE,BENT TABS OUT AND PULLED OFF FACE,TOOK 2 PANELS OUT IN BASEMENT DOORS TO GET TO BACK SIDE OF FURNANCE,TOOK OUT 2 SCREWS AND UNDD LP LINE,CUT WIRES AND PULLED OUT FURNANCE AND PUT ON BENCH AND RAN AND IT IS QUIET,SEALED METAL FLANGE IN FLOOR.BECAUSE IT WAS VIBRATING,PUT FURNANCE BACK IN PLACE AND REWIRED

r paper claims ~~only~~ use one pre-authorization number per warranty claim for
iple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

Pre-Authorization

3/30/20
12:09:32 PM

Job Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
8 3201816A	Decorative Wood	0.00	0.30	0.10		1	0.10	BACK TOGETHER, INSTALLED LP LINE AND 2 SCREWS AND 2 VENTS, SCREWED FACIA BACK ON AND BENT TABS BACK IN PLACE, RAN FURNANCE AND IT IS ALOT QUIETER. Correction: TOOK OUTSIDE COVER OFF, TOOK SCREWS OUT OF FURNANCE AROUND OUTSIDE PLATE, BENT TABS OUT AND PULLED OFF FACE, TOOK 2 PANELS OUT IN BASEMENT DOORS TO GET TO BACK SIDE OF FURNANCE, TOOK OUT 2 SCREWS AND UNID LP LINE, CUT WIRES AND PULLED OUT FURNANCE AND PUT ON BENCH AND RAN AND IT IS QUIET, SEALED METAL FLANGE IN FLOOR, BECAUSE IT WAS VIBRATING, PUT FURNANCE BACK IN PLACE AND REWIRED BACK TOGETHER, INSTALLED LP LINE AND 2 SCREWS AND 2 VENTS, SCREWED FACIA BACK ON AND BENT TABS BACK IN PLACE, RAN FURNANCE AND IT IS ALOT QUIETER. Cause: STAPLED ALL 3 PLACES IN PLACE. Correction: STAPLED ALL 3 PLACES IN PLACE.
3-Authorization number PA033994 10				<u>2.10</u>				

For paper claims ~~only~~, use one pre-authorization number per warranty claim for multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the