

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 1477975 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CAVB2PX028785 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 205 / 205 ITEM # ACAT303RKDSLE DEALER RO # 70136 CLAIM START DATE 03/30/2023 CLAIM END DATE 01/01/1900
-----------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Retail Date of Purchase	WARRANTY EXPIRATION DATE
-------------------------	--------------------------

Claim Line Details

Labor

Line# 1

Operation Code	Operational Description		
22-614-00-02-000678	Screen Door - Cargo Exterior/Door, Entry, Steps/No Tread Code/Adjust		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2023-03-30 14:19:25 :: SCREEN DOOR NEEDS ADJUSTED screen door wont latch loosened screws and pulled latch out from frame so door would latch.			
Model #	Dlr Sub Hrs	Sub Labor Amt	\$16.00
Serial #	Appr Hrs	Appr Labor Amt	\$16.00

Notes

Labor

Line# 2

Operation Code	Operational Description		
02-20-66-000664	Entry Door - RV - Adjust/Exterior/Entry Doors		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2023-03-30 14:20:35 :: MAIN ENTRY DOOR NEEDS ADJUSTED door wont latch loosened screws and pulled latch out from frame.			
Model #	Dlr Sub Hrs	Sub Labor Amt	\$16.00
Serial #	Appr Hrs	Appr Labor Amt	\$16.00

Notes

Labor

Line# 3

Operation Code	Operational Description		
60-138-01-00-001530	Sewer Cap Cover - Plumbing/Drainage System/Replace/No Tread Code		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2023-03-30 14:21:33 :: SEWER CAP HAS BROKEN LEGS INSTALL NEW SEWER CAP			
Model #	Dlr Sub Hrs	Sub Labor Amt	\$0.00
Serial #	Appr Hrs	Appr Labor Amt	\$0.00

Notes

Labor

Line# 4

Operation Code	Operational Description		
24-70-147-001769	TV Coax Cable - Repair/Appliances/Television		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2023-03-30 14:22:20 :: TV NOT PICKING UP CHANNELS tv did not pick up anything when testing. removed booster from wall to check connections. there is not a splitter installed to send signal to bedroom and outdoor coax hook up. installed splitter and made a small piece of coax to hook up to the booster. took a tester and hooked up to each line to make sure all			

connections were good. went on top of roof and removed top of antenna and found the coax cable had insulation wrapped around the wire. removed insulation. hooked up antenna. ran channel scan with shop tv and picked up local channels. secured booster to wall. tested all coax inputs with tv. cleaned up mess.

Model #	Dir Sub Hrs	2.00	Sub Labor Amt	\$320.00
Serial #	Appr Hrs	2.00	Appr Labor Amt	\$320.00

Notes

Submitted	Labor Amt	\$352.00
	Parts & Freight	\$0.00
	Total	\$352.00

Approved	Labor Amt	\$352.00
	Parts & Freight	\$0.00
	Total	\$352.00

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.