

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106  
 BASDEN RV CENTER INC  
 DBA AMERICAN RV CENTER  
 600 E BASELINE ROAD  
 EVANSVILLE, IN 47725  
 USA

CLAIM STATUS Authorized  
 CLAIM 1477740  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 5ZT2CAGC6PK005593  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 203 / 203  
 ITEM # BCAT184BHS  
 DEALER RO # 70150  
 CLAIM START DATE 03/30/2023  
 CLAIM END DATE 01/01/1900

Labor rate: \$160.00

**OWNER INFORMATION**

Retail Date of Purchase

WARRANTY EXPIRATION DATE

**Claim Line Details**

**Labor**

Line# 1      **Operation Code**      **Operational Description**  
 10-11-01-00-000205      Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2023-03-30 12:43:00 :: SILICONE ALL OVER SLIDE SEAL silicone on seal. removed with putty knife and mineral spirits.

Model #	Dlr Sub Hrs	0.10	Sub Labor Amt	\$16.00
Serial #	Appr Hrs	0.10	Appr Labor Amt	\$16.00

**Notes**  
 AUTHORIZED AS REQUESTED

**Labor**

Line# 2      **Operation Code**      **Operational Description**  
 10-11-01-00-000205      Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2023-03-30 12:44:55 :: BULB SEAL CAME OFF BOTTOM OF SLIDE RE INSTALL BULB SEAL. BULB SEAL WAS IN FRONT COMPARTMENT. REMOVED STAPLE FROM BOTTOM OF SLIDE SEAL. INSTALLED BULB SEAL ONTO TRACK. SECURED WITH SCREW AT BOTTOM.

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

**Notes**  
 AUTHORIZED AS REQUESTED

**Labor**

Line# 3      **Operation Code**      **Operational Description**  
 70-688-01-00-004012      GE Refrigerator, complete - Appliances/Refrigerator (GE)/Replace/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2023-03-30 12:46:08 :: FRIDGE IS NOT SECURED AT BOTTOM AND THERE IS NO BRACKET fridge didnt have a bracket. took a piece of trim and cut it down to length and ripped down to fit under the fridge. secured with screws.

Model #	GPV10FSNBSB	Dlr Sub Hrs	1.00	Sub Labor Amt	\$160.00
Serial #	LT551129	Appr Hrs	1.00	Appr Labor Amt	\$160.00

**Notes**  
 AUTHORIZED AS REQUESTED  
 NOT A REPLACEMENT IT WAS A REPAIR

**Labor**

Line# 4      **Operation Code**      **Operational Description**

20-57-24-00-000601

Sidewall - Exterior/Exterior Fiberglass Walls/Repair/No Tread Code

**Complaint, Cause, Correction**

Original Note : bhoffman@americanrvcenter.com, 2023-03-30 12:49:03 :: REMOVE SILICONE FROM DOOR SIDE WALL silcone all over wall. removed silicone with mineral spirits.

<b>Model #</b>	<b>Dir Sub Hrs</b>	0.10	<b>Sub Labor Amt</b>	\$16.00
<b>Serial #</b>	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b>	\$16.00

**Notes**

AUTHORIZED AS REQUESTED

**Submitted**

Labor Amt	\$224.00
Parts & Freight	\$0.00
<b>Total</b>	<b>\$224.00</b>

**Approved**

Labor Amt	\$224.00
Parts & Freight	\$0.00
<b>Total</b>	<b>\$224.00</b>

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.