



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 70150  
Promised Date:  
24 MAR 23

## CUSTOMER WORK ORDER

WO #: 70150

Customer: 1000 - BASDEN'S

AMERICAN RV -

Tag:

Author: PH

Location: 0331 CHECK PREAUTH

Stock #: 11259

Stock Desc: 2023 TT COACHMEN

CATALINA 184BHS

Chassis #: 5ZT2CAGC6PK005593

Serial #: 5ZT2CAGC6PK005593

Mileage: 0

Licence:

Invoice #:

Date In: 22 MAR 23

Promised: 31 MAR 23

Date Sched:

Completed: 30 MAR 23

Warr. Date:

### Job #SUMMERLAND - Internal

COMPLAINT: SUMMERLAND PDI

CAUSE: pdi

CORRECTION: checked brakes,tires,lug nuts,running lights,filled lp,ran lp drop test, installed battery box, checked electrical system,plumbing system, holding tanks, dewinterized, checked doors, cabinets, removed packaging from appliances,wrote down and took pics of model and serial numbers.

#### Labor

| Code | Description                 | Mechanic | Total |
|------|-----------------------------|----------|-------|
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |
| Z990 | MISC LABOUR CODE (EXTERNAL) | ZMS      | N/C   |

#### Parts

| Part # | Description           | Qty  | Price | Total |
|--------|-----------------------|------|-------|-------|
| 13034  | 55362 STD BATTERY BOX | 1.00 | N/C   | N/C   |

#### Other Services

| Code | Description | Qty  | Price | Total |
|------|-------------|------|-------|-------|
| LPG  | LP GAS      | 4.00 | N/C   | N/C   |

Subtotal for Job #SUMMERLAND: 0.00

### Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

\*\*\*INCLUDES 2 GALLONS OF ANTI-FREEZE\*\*\*

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

\*\*DE-WINTERIZATION IS NOT INCLUDED\*\*

NUMBER OF GALLONS USED \_\_\_\_\_

CAUSE: winterize

CORRECTION: ran a.f. through all lines and fixtures. drained holding tanks and water heater, bypassed water heater.

#### Labor

| Code | Description    | Mechanic | Total |
|------|----------------|----------|-------|
| Z990 | WINTERIZE UNIT | ZMS      | N/C   |
| Z990 | WINTERIZE UNIT | ZMS      | N/C   |

#### Parts

| Part # | Description               | Qty  | Price | Total |
|--------|---------------------------|------|-------|-------|
| 24181  | -50 RV ANTI-FREEZE GALLON | 2.00 | N/C   | N/C   |

Printed On: 3/30/2023 5:47:48PM

© 2023 Integrated Dealer Systems



Customer #:  
1000



W/O: 70150  
Promised Date:  
31 MAR 23



Customer #:  
1000



#### Other Services

| Code                      | Description   | Qty  | Price | Total |
|---------------------------|---------------|------|-------|-------|
| SS                        | SHOP SUPPLIES | 1.00 | N/C   | N/C   |
| Subtotal for Job #WINTER: |               |      |       | 0.00  |

#### Job #1 - Warranty

COMPLAINT: SILICONE ALL OVER SLIDE SEAL

CAUSE: silicone on seal.

CORRECTION: removed with putty knife and mineral spirits.

#### Labor

| Code                 | Description                 | Mechanic | Total |
|----------------------|-----------------------------|----------|-------|
| Z990                 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 16.00 |
| Subtotal for Job #1: |                             |          | 16.00 |

#### Job #2 - Warranty

COMPLAINT: BULB SEAL CAME OFF BOTTOM OF SLIDE

CAUSE: RE INSTALL BULB SEAL. BULB SEAL WAS IN FRONT COMPARTMENT.

CORRECTION: REMOVED STAPLE FROM BOTTOM OF SLIDE SEAL. INSTALLED BULB SEAL ONTO TRACK. SECURED WITH SCREW AT BOTTOM.

#### Labor

| Code                 | Description                 | Mechanic | Total |
|----------------------|-----------------------------|----------|-------|
| Z990                 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 32.00 |
| Subtotal for Job #2: |                             |          | 32.00 |

#### Job #3 - Warranty

COMPLAINT: FRIDGE IS NOT SECURED AT BOTTOM AND THERE IS NO BRACKET

CAUSE: fridge didnt have a bracket.

CORRECTION: took a piece of trim and cut it down to length and ripped down to fit under the fridge. secured with screws.

#### Labor

| Code                 | Description                 | Mechanic | Total  |
|----------------------|-----------------------------|----------|--------|
| Z990                 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 160.00 |
| Subtotal for Job #3: |                             |          | 160.00 |

#### Job #4 - Warranty

COMPLAINT: REMOVE SILICONE FROM DOOR SIDE WALL

CAUSE: silicone all over wall.

CORRECTION: removed silicone with mineral spirits.

#### Labor

| Code                 | Description                 | Mechanic | Total |
|----------------------|-----------------------------|----------|-------|
| Z990                 | MISC LABOUR CODE (EXTERNAL) | ZMS      | 16.00 |
| Subtotal for Job #4: |                             |          | 16.00 |



W/O: 70150  
Promised Date:  
31 MAR 23



Customer #:  
1000



|                          |               |
|--------------------------|---------------|
| Parts Total:             | 0.00          |
| Labour Total:            | 224.00        |
| Sublet Total:            | 0.00          |
| Extras Total:            | 0.00          |
| <b>WORK ORDER TOTAL:</b> | <b>224.00</b> |

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 30 Mar 2023

