

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1481729
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKY2XPK086674
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT23DBH-94
		DEALER RO #	70221
		CLAIM START DATE	04/03/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 10-40-01-16-004006	Operational Description Stand-Off Bracket, Inside or Outside - Frame & Chassis/Slide Out System (Norco, ACCU-Slide, BAL)/Replace/Structure
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-04-03 15:33:43 :: THE SLIDE ROOM CABLE POPPED WHEN RUNNING THE ROOM IN FOUND ALL BOLD BROKEN OFF HAD TO REMOUNT WHERE THE BRACKET BROKE OFF HAD TO LOOSEN CABLES AND CHAIN TO GET CABLE BACK IN THE GROOVE THEN READJUSTED THE ROOM RAN ROOM IN AND OUT TO MAKE SURE IT WAS OPERATING GOOD. Additional Note : bhoffman@americanrvcenter.com, 2023-04-03 15:35:11 :: HAD TO DRILL THE SCREWS OUT ALL THE HEADS BROKE OFF	
	Model #	Dlr Sub Hrs 2.50 Sub Labor Amt \$400.00
	Serial #	Appr Hrs 2.00 Appr Labor Amt \$320.00
	Notes Authorized for 2.00 hrs.	

Labor

Line# 2	Operation Code 20-69-02-00-000705	Operational Description Compartment Door - Exterior/Compartment Doors/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-04-03 15:35:33 :: OUTSIDE FRIDGE DOOR WILL NOT OPEN (NOD) OUTSIDE REFRIG. DOOR WILL NOT OPEN (NOD). Refrig door hits drop down compartment door and will not open. Removed screw and bracket securing refrig in place. Raised front of refrig and adjusted front screw in feet to raise front of refrig. Checked operation of door. Door now opens. Resecured bracket with screw.	
	Model #	Dlr Sub Hrs 0.20 Sub Labor Amt \$32.00
	Serial #	Appr Hrs 0.20 Appr Labor Amt \$32.00
	Notes	

Labor

Line# 3	Operation Code 30-99-24-00-001015	Operational Description Mini-Blind - Interior/Soft Goods/Repair/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-04-03 15:36:53 :: ROADSIDE BEDROOM SHADE WONT PULL DOWN (NOD) Checked operation of bedroom shade. Left side string has a triple knot in string. Clamped shade to secure in up position. Removed string anchor at bottom. Picked out triple knot in string. Remounted string at bottom. Removed clamp and checked operation of shade. OK.	
	Model #	Dlr Sub Hrs 0.20 Sub Labor Amt \$32.00
	Serial #	Appr Hrs 0.20 Appr Labor Amt \$32.00

Notes
Authorized as requested.

Submitted	Labor Amt	\$464.00
	Parts & Freight	\$0.00
	Total	\$464.00

Approved	Labor Amt	\$384.00
	Parts & Freight	\$0.00
	Total	\$384.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	