



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70221
Promised Date:
26 APR 23



Customer #:
1000



CUSTOMER WORK ORDER

WO #: 70221

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: BH

Location: 0405 BH TO CLOSE

Stock #: 11077

Stock Desc: 2023 TT FOREST RIVER

CHEROKEE GREY WOLF 23DBH

Chassis #: 4X4TCKY2XPK086674

Serial #: 4X4TCKY2XPK086674

Mileage: 0

Licence:

Invoice #:

Date In: 30 MAR 23

Promised: 29 APR 23

Date Sched:

Completed: 31 MAR 23

Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: THE SLIDE ROOM CABLE POPPED WHEN RUNNING THE ROOM IN

CORRECTION: HAD TO REMOUNT WHERE THE BRACKET BROKE OFF HAD TO LOOSEN CABLES AND CHAIN TO GET CABLE BACK IN THE GROOVE THEN READJUSTED THE ROOM RAN ROOM IN AND OUT TO MAKE SURE IT WAS OPERATING GOOD.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	160.00

Subtotal for Job #1: 320.00

Job #2 - Warranty

COMPLAINT: OUTSIDE FRIDGE DOOR WILL NOT OPEN (NOD)

CAUSE: OUTSIDE REFRIG. DOOR WILL NOT OPEN (NOD).

CORRECTION: Refrig door hits drop down compartment door and will not open. Removed screw and bracket securing refrig in place. Raised front of refrig and adjusted front screw in feet to raise front of refrig. Checked operation of door. Door now opens. Resecured bracket with screw.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	32.00



W/O: 70221
Promised Date:
29 APR 23



Customer #:
1000



Subtotal for Job #2: 32.00

Job #3 - Warranty

COMPLAINT: ROADSIDE BEDROOM SHADE WONT PULL DOWN (NOD)

CAUSE: ROADSIDE BEDROOM SHASE WON'T PULL DOWN (NOD)

CORRECTION: Checked operation of bedroom shade. Left side string has a triple knot in string. Clamped shade to secure in up position. Removed string anchor at bottom. Picked out triple knot in string. Remounted string at bottom. Removed clamp and checked operation of shade. OK.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	32.00
Subtotal for Job #3:			32.00

Parts Total:	0.00
Labour Total:	384.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	384.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 05 Apr 2023

Customer Signature : _____

