

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 70240  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 11262 - 2023 CHEROKEE GREY WOLF 29TE 4X4TCKE23PX161612  
VIN: 4X4TCKE23PX161612 HIN: SER#: 4X4TCKE23PX161612  
Mileage: 0 Work Order Comp: 12 APR 23  
Auth. No: Dealer #:  
Warr. Date: Work Order Date: 03 APR 23 Inv #: 389692

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*

- 70240 7 THE ZEBRA BLIND BEHIND THE COUCH WILL NOT STAY UP  
THE ZEBRA BLIND BEHIND THE COUCH WOULD NOT STAY IN THE DOWN  
POSITION. I TOOK THE VALANCE DOWN ALONG WITH THE BLIND. TRIED TO  
ADJUST THE TENSION ON THE BRACKETS THE RIGHT SIDE BRACKET HAD NO  
TENSION IN THE GEARS THE LEFT SIDE DID BUT THAT WASNT ENOUGH TO  
LET THE BLID WORK PROPERLY. DENNY SAID TO JUST ORDER A NEW ONE  
AND INSTALL IT. I UP IN A PURCHJAS ORDER IN ON 4-4-23 THE BLIND  
SIZE IS 64X26
- 70240 2 ADJUST FRONT DOOR AND SCREEN DOOR.  
I HAD TO ADJUST THE HING SIDE OF THE DOOR IT WAS HITTING THE DOOR  
FRAME. SCREEN DOOR STRIKE NEEDED ADJUSTED AND THEY HAD LEFT THE  
PLASTIC SPACERS ON THE TOP OF THE DOOR
- 70240 3 ADJUST BRACKET ON STEPS  
I HAD TO MOVE THE 2 LATCHING BRACKETS IN SOME. WHEN YOU WOULD  
FOLD DOWN THE STEPS THEY WERE RUBBING ON BOTH SIDES.
- 70240 4 THE PANTRY DOOR WILL NOT LATCH  
shimmed out the strick plate with 2 washers. the door stays  
latched now
- 70240 5 THE BATHROOM DOOR WILL NOT LATCH  
ADJUSTED KNOB IT WAS WAY TO TIGHT, SHIMMED OUT STRIKE PLATE WITH  
2 WASHERS. DOOR LATCHES FINE NOW

Claim : 70240

```

*****
WO #      Job #   Description          JOB INFORMATION
*****
70240      6     THE LEG ON THE TABLE ARE MISSING SCREWS.
          3 SCREWS HAD FALLEN OUT FROM THE BOTTOM OF THE TABLE. THE REST OF
          THE SCREWS WERE STRIPPD. I REMOVED 12 SCREWS AND REPLACED WITH 12
          6X1/4 SCREWS. THE TABLE IS MORE SECURED NOW

70240      8     THE WATER HEATER DOOR WILL NOT CLOSE PROPERLY.
          THE DOOR ON WATER HEATER WOULD NOT CLOSE PROPERLY BECAUSE THE
          VENT PIPE WAS HITTING THE DOOR I UNMOUNTED THE WATER HEATER BY 4
          SCREWS. I HAD TO MOVE IT COUNTER CLOCKWISE TO GET THE VENT SO IT
          WOULD GO THROUGH THE DOOR PROPERLY. SCREWD IT BACK DOWN . THE
          DOOR IS WORKING PROPERLY NOW.

```

```

*****
Part No    Job#   Description          PARTS          Qty    Price    Total
*****
F100141513  7     SHADE, 64" X 24" ZEBRA SHADE / 20  1.00    80.78    80.78

```

```

*****
Lab Code   Job#   Description          LABOUR          Hrs    Rate    Total
*****
Z990       7     MISC LABOUR CODE (EXTERNAL)          0.00   160.00    0.00
Z990       7     MISC LABOUR CODE (EXTERNAL)          0.20   160.00   32.00
Z990       7     MISC LABOUR CODE (EXTERNAL)          0.00   160.00    0.00
Z990       7     MISC LABOUR CODE (EXTERNAL)          0.00   160.00    0.00
Z990       2     MISC LABOUR CODE (EXTERNAL)          0.60   160.00   96.00
Z990       3     MISC LABOUR CODE (EXTERNAL)          0.10   160.00   16.00
Z990       4     MISC LABOUR CODE (EXTERNAL)          0.20   160.00   32.00
Z990       5     MISC LABOUR CODE (EXTERNAL)          0.00   160.00    0.00
Z990       5     MISC LABOUR CODE (EXTERNAL)          0.20   160.00   32.00
Z990       6     MISC LABOUR CODE (EXTERNAL)          0.60   160.00   96.00
Z990       8     MISC LABOUR CODE (EXTERNAL)          0.00   160.00    0.00
Z990       8     MISC LABOUR CODE (EXTERNAL)          0.50   160.00   80.00

```

```

*****
Excode    Job#   Description          EXTRAS          Qty    Price    Total
*****
FRT       7     UPS-SHADE                                1.00   31.46   31.46

```

```

Parts Total:      80.78
Labour Total:     384.00
Sublet Total:      0.00
Extras Total:     31.46

```

>>>> Claim Total: 496.24

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_