

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 70246  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 11264 - 2023 CATALINA 283RKSLE 5ZT2CATB3PX028913

VIN: 5ZT2CATB3PX028913 HIN:

SER#: 5ZT2CATB3PX028913

Mileage: 0

Work Order Comp: 12 APR 23

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 03 APR 23

Inv #: 389704

\*\*\*\*\*

WO # Job # Description JOB INFORMATION

\*\*\*\*\*

70246 1 BATHROOM DOOR RUBBING  
BATHROOM DOOR RUBBING AGAINST STRIKE PLATE. STRIKE PLATE NEEDS  
ADJUSTED. LOSSENEED SCREWS AND READJUSTED STRIKE PLATE TO ALLW  
DOOR TO SHUT PROOPERLEY AND NOT RUB  
BATHROOM DOOR RUBBING AGAINST STRIKE PLATE. STRIKE PLATE NEEDS  
ADJUSTED. LOSSENEED SCREWS AND READJUSTED STRIKE PLATE TO ALLW  
DOOR TO SHUT PROOPERLEY AND NOT RUB

70246 2 BEDROOM DRAWER NOT SHUTTING  
BEDROOM DRAWER NUT SHUUTING AS IT WAS OFF THE TRACK. REINSTALLE  
PROPERELY ON THE TRACK THEN TESTED  
BEDROOM DRAWER NUT SHUUTING AS IT WAS OFF THE TRACK. REINSTALLE  
PROPERELY ON THE TRACK THEN TESTED

70246 3 SHOWER SURROUND NEEDS SEALED  
shower surround needed sealed up on top. sealed up shower  
surround with clear silicone  
shower surround needed sealed up on top. sealed up shower  
surround with clear silicone

70246 4 KITCHEN SINK DRAIN PIPE NOT CONNECTED  
KITCHEN SINK DRAIN PIPE WASNT SCREWED ON FROM FACTORY, CAUSING A  
LEAK WHEN RUNNING WATER. REATTACHED FITTING AND TESTED  
KITCHEN SINK DRAIN PIPE WASNT SCREWED ON FROM FACTORY, CAUSING A  
LEAK WHEN RUNNING WATER. REATTACHED FITTING AND TESTED

Claim : 70246

\*\*\*\*\*

WO # Job # Description JOB INFORMATION  
\*\*\*\*\*

70246 5 FREEZER DOOR HITTING LATCH  
FREEZER DOOR HITTING LATCH WHEN YOU GO TO CLOSE IT. LATCH NEEDS  
TO BE ADJUSTED DOWN. ADJUSTED LATCH DOWN SO THAT FREEZER DOOR CAN  
SHUT PROPERLEY  
FREEZER DOOR HITTING LATCH WHEN YOU GO TO CLOSE IT. LATCH NEEDS  
TO BE ADJUSTED DOWN. ADJUSTED LATCH DOWN SO THAT FREEZER DOOR CAN  
SHUT PROPERLEY

70246 6 FRIDGE SWITCH NOT ATTACHED  
fridge switch was not attached all the way. reattached switch  
properley and tested  
fridge switch was not attached all the way. reattached switch  
properley and tested

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.10	160.00	16.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.15	160.00	24.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.30	160.00	48.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.05	160.00	8.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00

Parts Total: 0.00  
Labour Total: 160.00  
Sublet Total: 0.00  
Extras Total: 0.00

>>>> Claim Total: 160.00

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_