



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70253
Promised Date:



Customer #:
53271



CUSTOMER WORK ORDER

WO #: 70253

Customer: 53271 - MARSHALL, JOHN

M. - 859-494-3105

Tag:

Author: CAM

Location: 0427 CHECK PREAUTH

Stock #: 11152

Stock Desc: 2023 TT KEYSTONE

COUGAR HALF-TON 30BHS

Chassis #: 4YDTCGP26PV505507

Serial #: 4YDTCGP26PV505507

Mileage: 0

Licence:

Invoice #:

Date In: 03 APR 23

Promised: 29 APR 23

Date Sched:

Completed: 26 APR 23

Warr. Date: 21 APR 23

Job #1 - Internal

COMPLAINT: TIRE-LINC INSTALLED

CAUSE: TIRE-LINK INSTALLED.

CORRECTION: Installed Tire-Links on all (4) tires.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts Part #	Description	Qty	Price	Total
5382	TIRE LINC TIRE PRESSURE AND TEMPERATURE MONITORING SYSTEM	1.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Internal

COMPLAINT: REMOVE VENT IN BATHROOM AND REPLACE WITH POWER VENT W/COVER (WHITE)

CORRECTION: removed old vent in bunk area . had to scrape and peel off old sealant. then had to find wires that i could splice into . once found installed new vent and screwed in then connected wires and tested function after that, inserted sgroud and dichord around the vent

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Parts Part #	Description	Qty	Price	Total
22-8890	MAXXFAN DELUXE, BUILT-IN RAIN SHIELD, 4=SPEED MANUAL LIFT, WHITE LID EXHAUST ONL	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	2.00	N/C	N/C



W/O: 70253
Promised Date:
29 APR 23



Customer #:
53271



Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: REMOVE VENT IN BUNK AREA AND REPLACE
WITH POWER FAN W/COVER. (SMOKE)

CAUSE: removed old vent in bunk area . had to scrape and peel off old sealant. then had to find wires that i
could splice into . once found installed new vent and screwed in then connected wires and tested function
after that, inserted sgroud and dichord around the vent

CORRECTION: removed old vent in bunk area . had to scrape and peel off old sealant. then had to find
wires that i could splice into . once found installed new vent and screwed in then connected wires and
tested function after that, inserted sgroud and dichord around the vent

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		RAB	N/C

Parts				
Part #	Description	Qty	Price	Total
22-8891	MAXX FAN DELUXE - SMOKE - W/RAINSHIELD	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT - PDI NEW TRAVEL TRAILER.

CORRECTION: Moved unit into shop from sold area. Filled LP tanks. Checked all exterior lights and
brakes. Checked lug nuts and set tire pressure at 80 psi. Recorded all tire serial numbers. Checked all
three entrance doors. Checked all compartment doors. Applied all company decals. Checked awning and
roof. Checked all windows and blinds. Checked all electrical outlets and GFCI outlets. Checked all USB
outlets. Added water to fresh water tank and flushed antifreeze from water lines and faucets. Checked all
water lines and faucets for leaks. Performed LP drop test and set LP pressure at 11 in.wc. Filled all
holding tanks and checked monitor panel. Made up winterizing hose for water pump. Checked outside
grille. Checked Radio/DVD/CD Player. Checked Fireplace. Checked both air conditioners. Checked TV
Antenna and Main TV. Used test TV at all other locations. All working. Recorded most of serial numbers.

Labor				
Code	Description		Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)		DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)		DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)		DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)		DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)		DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)		DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)		DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)		DKM	N/C

Parts				
Part #	Description	Qty	Price	Total
72-0839	Fresh Water Adapter Fitting; BestPEX; 1/2 Inch PEX x 1/2 Inch Female Pipe Thread Plastic Swivel End Nut	1.00	N/C	N/C

Other Services

	Description	Qty	Price	Total
Code				
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00





Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT - FINAL PDI ON NEW TRAVEL TRAILER.

CORRECTION: Dumped all holding tanks. Reset auto leveling jacks (2) times. Jacks now auto leveling the correct way.

Labor		Mechanic	Total
Code	Description		
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
Z990	MISCELLANEOUS REPAIR	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts				
Part #	Description	Qty	Price	Total
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C
10-7090	1pc 1/2" PLUG CAP	2.00	N/C	N/C
Subtotal for Job #FPDINTT:				0.00

Job #EQUALIZER1000 - Internal

COMPLAINT: INSTALL 1000# EQUALIZER HITCH

CORRECTION: SETUP E2 HITCH ON F350 WITH A 3" RECEIVER. CUSTOMER HAD A 3" TO 2.5" ADAPTER. WE DID NOT HAVE A DROP BAR TO FIT THE TRUCK AND HAD TO USE A 2ND ADAPTER. I LET THE CUSTOMER KNOW THAT HE SHOULD ORDER THE RIGHT DROP BAR FOR THE HITCH TO FIT IN THE TRUCK WITHOUT AN ADAPTER. HITCH MIGHT NEED TO BE RESET AFTER INSTALLING A BIGGER DROP BAR. HOOKED TRUCK UP TO TRAILER AND ADJUSTED AS NEEDED.

Labor		Mechanic	Total
Code	Description		
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Parts				
Part #	Description	Qty	Price	Total
710831	EQUALIZER 1000#/10000# ADJ. HITCH	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
PARTS	6175 SHANK 90-01-4700	1.00	N/C	N/C
Subtotal for Job #EQUALIZER1000:				0.00

Job #CAMERA - Internal

COMPLAINT: INSTALL WIRELESS CAMERA

CORRECTION: RYAN INSTALLED CAMERA

Labor		Mechanic	Total
Code	Description		
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Parts				
Part #	Description	Qty	Price	Total
729936	FURRION 7" REAR CAMERA SYSTEM	1.00	N/C	N/C
500627	CLEAR SIKASIL PLUS	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C





Subtotal for Job #CAMERA: 0.00

Job #WALK - Internal
 COMPLAINT: WALK THRU

CORRECTION: DID WALK THRU,CUSTOMER HAD LOTS OF QUESTIONS,SINCE THIS UNIT WAS SPECIAL ORDER WITH SOLAR AND EXTRA BATTERIES,HAD TO CHANGE DROP BAR TO 3 INCH,BROUGHT TRUCK AROUND AND GIVE KEYS TO CUSTOMER.
 Estimated Amount: 180.00

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #WALK:			0.00

Job #4 - Internal
 COMPLAINT: USB OUTLETS IN FRONT BEDROOM NOT WORKING

CAUSE: USB OUTLETS IN FRONT BEDROOM NOT WORKING.

CORRECTION: CHECKED AFTER BATTERY DISCONNECT WAS ON THEY ARE ALL WORKING NOW.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		N/C
Subtotal for Job #4:			0.00

Job #5 - Warranty
 COMPLAINT: FLOOR TRIM IN FRONT BEDROOM COMING OFF AT FLOOR

CAUSE: FLOOR TRIM IN FRONT BEDROOM COMING OFF AT FLOOR.

CORRECTION: Reattached floor trim with brad nails.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	16.00
Subtotal for Job #5:			16.00

Job #6 - Warranty
 COMPLAINT: OUTSIDE SHOWER HEAD LEAKS

CAUSE: OUTSIDE SHOWER HEAD LEAKS.

CORRECTION: Removed shower head from shower hose. Washer surface on shower head has a bad spot that is not sealing. Replaced shower head.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	32.00
Subtotal for Job #6:			52.14

Parts Part #	Description	Qty	Price	Total
680727	DF-SA130-BK BLACK 60" SHOWER HANDLE KIT	1.00	20.14	20.14
Subtotal for Job #6:				52.14



W/O: 70253
Promised Date:
29 APR 23



Parts Total:	20.14
Labour Total:	48.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	68.14

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 26 Apr 2023

Customer Signature : _____

Customer #:
53271

