

e-Authorization

4/11/20
10:50:13

e-Authorization number PA03408584 Reference no: 70263 Status: Approved Approved by anglr Approved date 4/11/2023
 Authorizing Name Address Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTCGR28PV505313
 600 E Baseline Rd
 Evansville, IN 47725

Item #	Root of operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	1200324B	Bumper Cover	0.00	0.10	0.10		1	0.30	Complaint:bumper cap missing Cause:BUMPER CAPS MISSING. Correction:Installed new bumper caps to replace missing caps.
2	2302218A	Compartment Doc	0.00	0.40	0.20		1	0.20	Complaint:BED SLIDE OUTSIDE COMPARTMENT DOOR WONT CLOSE Cause:BED SLODE OUTSIDE COMPARTMENT DOOR WONT CLOSE. Correction:Latch mounted on left side of door is bent out of shape. Removed from door frame. Found three sets of holes from factory trying to get door to latch. Straightened door frame and remounted latch plate. Checked operation of left side latch. Now closes and latches.
3	2104428A	Slide Out - Box - f	0.00	0.60	0.20		2	0.10	Complaint:FACIA BOARDS LOOSE ON 2 SLIDE OUTS (NOD) Cause:FACIA BOARDS LOOSE ON 2 SLIDE OUTS (NOD) Correction:Facia boards loose on kitchen slide and dinette slide. Reattached facia boards with small staples and filled holes with matching putty.

3-Authorization number PA03408584

0.50

KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.

For paper claims only, use one pre-authorization number per warranty claim for

multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the