



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

WO: 70263

CUSTOMER WORK ORDER

WO #: 70263

Customer: 1000 - BASDEN'S

AMERICAN RV -

Tag:

Author: PH

Location: 0413 CHECK PREAUTH

Stock #: 11155

Stock Desc: 2023 TT KEYSTONE

COUGAR HALF-TON 33RLI

Chassis #: 4YDTCGR28PV505313

Serial #: 4YDTCGR28PV505313

Mileage: 0

Licence:

Invoice #:

Date In: 04 APR 23

Promised:

Date Sched:

Completed: 11 APR 23

Warr. Date:



Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

VIN: PV505313

CAUSE: PDINTT - PDI NEW TRAVEL TRAILER: PV505313

CORRECTION: Moved unit into shop from sales lot. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Checked entrance door and all compartment doors. Checked both awnings. Checked roof. Lubbed lock on battery box so that it would open. Operated all auto leveling jacks. Reset system to auto level. Checked all cabinets and drawers. Checked all windows and blinds. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Checked converter output. Added water to fresh water tank. Flushed antifreeze from water lines and faucets. Checked all water lines and faucets for leaks. Filled all holding tanks and checked monitor panel. Applied all company decals. Drained all holding tanks. Checked TV Antenna, MainTV And all TV locations. Checked Radio/DVD/CD player. Checked Fireplace. Took pictures and recorded all serial numbers. Moved unit to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: bumper cap missing

CAUSE: BUMPER CAPS MISSING.

CORRECTION: Installed new bumper caps to replace missing caps.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	16.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



Customer #:
1000



11-0181

40303 BUMPER CAPS 2-PACK

1.00

4.99

4.99

Subtotal for Job #1:

20.99

Job #2 - Warranty

COMPLAINT: BED SLIDE OUTSIDE COMPARTMENT DOOR WONT CLOSE

CAUSE: BED SLODE OUTSIDE COMPARTMENT DOOR WONT CLOSE.

CORRECTION: Latch mounted on left side of door is bent out of shape. Removed from door frame.
Found three sets of holes from factory trying to get door to latch. Straightened door frame and remounted latch plate. Checked operation of left side latch. Now closes and latches.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	32.00
Subtotal for Job #2:			32.00

Job #3 - Warranty

COMPLAINT: FACIA BOARDS LOOSE ON 2 SLIDE OUTS (NOD)

CAUSE: FACIA BOARDS LOOSE ON 2 SLIDE OUTS (NOD)

CORRECTION: Facia boards loose on kitchen slide and dinette slide. Reattached facia boards with small staples and filled holes with matching putty.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	32.00
Subtotal for Job #3:			32.00

Parts Total: 4.99

Labour Total: 80.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 84.99

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 11 Apr 2023

W/O: 70263



Customer #: 1000

